

STREET #	105
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301015
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	IHSS (HD); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	Fine, simple iteration combination of the Italianate and Greek Revival styles within the district.
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate	PLAN	rectangular
DETAILS	Greek Revival	NO OF STORIES	2
BEGINYEAR	1874	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	full front/side
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum/vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	glass block
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	2/2 vertical

SIGNIFICANT FEATURES	Front gable roof with wood frieze; pedimented heads at window openings.
-----------------------------	---

ALTERATIONS	Replacement front door (not historic); front porch add./replacement S. porch (historic--c. 1905); S side door, surround, & canopy/stoop (not historic); glass block in basement windows (not historic). Post-2007 -- 2/2 double-hung Aluminum replacement windows throughout; non-historic north entrance porch replaced with historically compatible entry porch; new detached garage.
--------------------	---

HISTORIC INFORMATION

HISTORIC NAME	Barr, Samuel house
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	Barr, Samuel
ARCHITECT SOURCE	
HISTORIC INFO	1892 Sanborn Map shows no front porch; 1898 map shows front entry porch. Current porch has no entry/steps. [from A GUIDE TO CHICAGO'S HISTORIC SUBURBS, p. 401] "This clapboard farmhouse, built in 1874, has the massing and details reminiscent of Greek Revival, but with pedimented window heads characteristic of the 1870s date. Added at the turn of the century was the porch with its four, standard, Tuscan columns. The west end of the building
PERMITS	
LANDSCAPE	Northwest corner of Franklin and Ellsworth; front and south sidewalks; side driveway; similar setbacks; mature trees
COA DATE	9/28/2012
COA DECISION	COA #12-3641 - replacement of [north] side entry porch (approved 10/2/2012)

☒ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER	Lara Ramsey	SURVEYDATE
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA



☒ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

2/2 double-hung Aluminum replacement windows throughout

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	113
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301014
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	PS
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1888	ROOF TYPE	Front gable
OTHER YEAR	1908 (addition)	ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Owners	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	side entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed/caseme
		WINDOW CONFIG	4/4; 1/1; multi/1; 3-light
SIGNIFICANT FEATURES	Front gable with south side gable bay (1st story cutaway corners on south bay); concrete block one-car detached garage		
ALTERATIONS	Aluminum siding (1997); replacement front door/surround/stoop (not historic); 3-sided front window bay (historic); 2 story south/rear addition with entry (1908); replacement windows in original openings (historic); replacement 2nd story window above entry in downsized opening (historic); 2 & 1 story rear additions. Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

11/20/2025

NAPERVILLE HISTORIC DISTRICT

STREET #	117
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301013
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	Rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1890	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	House History Questionnaire	FOUNDATION	Concrete block
WALL MATERIAL (current)	Aluminum	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1

SIGNIFICANT FEATURES	Front gable roof; historic 1/1 wood windows; rear/south side 2 story bay
----------------------	--

ALTERATIONS	Front porch (historic); rear/south side entry porch (not historic); Aluminum siding; fixed shutters (not historic); replacement front door (not historic). Post-2007 -- no changes.
-------------	---

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO
House history questionnaire submitted by owner includes chain of title/ownership information and tax records. Title research indicates that the property was owned by Samuel Barr at the time the house was constructed.

PERMITS

LANDSCAPE
Midblock on west side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	119
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301012
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	Unusual combination of the Craftsman and Prairie styles in the historic district, with distinctive 2nd story sun porch.
INTEGRITY	minor alterations		
SECONDARY STRUCTURE	detached		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman	PLAN	Rectangular
DETAILS	Prairie	NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Gable on hip
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	1/1; 1-light

SIGNIFICANT FEATURES	Hipped roof with offset front gable; overhanging eaves; inset front porch w/ cast concrete columns on concrete block piers; 2nd story sun porch.
----------------------	--

ALTERATIONS	Post-2007 -- house appeared to be vacant/under renovation during 2007 survey. Post-2007 alterations include 2nd story rear addition; 1/1 aluminum replacement windows on front and side elevations, some in altered openings; aluminum single-light replacement windows in 2nd story sun porch; replacement front doors at center and north end entries under front porch; north end enclosure of front porch evident in 2007 survey removed; cast-stone steps to front porch flanked by brick planters; wrought iron railings added above north and south knee walls at front porch.
-------------	---

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO			
PERMITS			
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees		
COA DATE	8/20/2018;4/26/2019		
COA DECISION	COA #18-3335 - Replacing door with window and in-kind replacement matching existing window (approved 8/22/2018); COA #19-1196 - remove window replace with door - door existed prior to 2018 (approved 4/26/2019)		
☒ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	



☒ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: All work listed in alterations with the exception of the replacement front door in north end entry under porch

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	125
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301011
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	Y
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	IHSS (P); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	Fine local example of the Italianate style, featuring elegant window surrounds topped with triangular pediments. Listed on IHSS (P).
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1870	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	GUIDE TO CHICAGO'S SUBURBS	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	2/2 vertical
SIGNIFICANT FEATURES	Front gable bay w/ south 2 story side gable wing; wood frieze; historic 2/2 vertical wood windows 2/2 triangular pediment lintels; front porch w/ carved wood supports & brackets; 2 story square south window bay; double entry doors		
ALTERATIONS	Rear 2nd story addition; rear screened porch addition. Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

11/20/2025

NAPERVILLE HISTORIC DISTRICT

STREET #	129
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301010
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	major alterations and/or addition(s)		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	irregular
DETAILS	Italianate	NO OF STORIES	2
BEGINYEAR	1866	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	GUIDE TO CHICAGO'S HISTORIC SUBURBS	FOUNDATION	Stone/concrete
WALL MATERIAL (current)	Wood	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	2/2 vertical; 1/1; multi-lig

SIGNIFICANT FEATURES	Original front gable roof and rectangular massing of section of original house (east end).
----------------------	--

ALTERATIONS	Large 2 story rear addition (not historic); entry bay and porch (not historic); replacement windows in altered openings (not historic); replacement siding; window surrounds appear to be non-historic replacements, although they may have been modeled on historic surrounds. Post-2007 -- no changes.
-------------	--

HISTORIC INFORMATION

HISTORIC NAME	Leffler, Jeremiah House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	Naperville Historic District Website lists 129 N. Ellsworth as Jeremiah Leffler House, built in 1866. Building included in A GUIDE TO CHICAGO'S HISTORIC SUBURBS ON WHEELS AND ON FOOT, p. 401 (Naperville #6).
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATE	
COA DECISION	
☐ IN COMPLIANCE WITH COA?	
COA COMPLIANCE NOTES:	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS
SURVEYDATE	
SURVEYAREA	



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

--

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	130
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818302012
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	NC
Listed on existing SURVEY?	IHSS (HD); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	major alterations and/or addition(s)		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate (altered)	PLAN	irregular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	1872	ROOF TYPE	Combination
OTHER YEAR	1903/1990s	ROOF MATERIAL	Wood - shingle
DATESOURCE	NHS Plaque/GUIDE TO CHICAGO'S HISTORIC SUBUR	FOUNDATION	Stone
WALL MATERIAL (current)	Brick	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Wood
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; multi-light
SIGNIFICANT FEATURES	Front gable portion is original house (windows on first story appear historic); round arch window openings w/ center keystones; half round window under gable; round arch front entry; historic two-story south/rear addition constructed in 1903 (addition originally featured a second west-facing porch)		
ALTERATIONS	Paired brackets & dentils appear to be later (may be restoration); replacement windows on 2nd story or original structure (not historic); replacement door & transom (not historic); large 2 story S. side addition w/ corner tower (not historic--1990s); replacement porch (not historic-1990s); 1 story north bay addition (not historic); segmental arch window on 2nd story north elevation (not historic); chimney (not historic); rear screened porch addition (not historic). Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO According to history of the house in Naperville Heritage Society address file, the house was built in 1872. See IHSS photograph for original massing of house. According to A GUIDE TO CHICAGO'S HISTORIC SUBURBS (p. 401-2), the south/rear addition was constructed in 1903 and featured a west-facing porch. The porch was removed when the large 2-story addition with corner tower was constructed in the 1990s.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; parking lot to south; similar setbacks; mature trees

COA DATE

COA DECISION

☐ IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	133
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818301009
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	IHSS (P); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good/fair	REASON for SIGNIFICANCE	
INTEGRITY	major alterations and/or addition(s)		
SECONDARY STRUCTURE	shed		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Greek Revival	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1860	ROOF TYPE	Front gable
OTHER YEAR	c. 1975	ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor/IHSS	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	
WALL MATERIAL 2 (current)	Stone veneer	WINDOW MATERIAL	Aluminum/vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	6/1; 1/1
SIGNIFICANT FEATURES	Front gable roof and rectangular massing		
ALTERATIONS	Aluminum siding (not historic); stone veneer on 1st story façade (not historic); 1 story rear addition. Post-2007 -- 6/1 vinyl replacement windows in existing openings; replacement front door; aluminum siding around first story windows at west end of south elevation replaced.		

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO			
PERMITS			
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fence		
COA DATE			
COA DECISION			
☐ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	



☒ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

6/1 vinyl replacement windows in existing openings; replacement front door; aluminum siding around first story windows at west end of south elevation replaced.

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET # 135
DIRECTION N
STREET ELLSWORTH
SUFFIX ST
PIN 0818301008

LOCAL SIGNIFICANCE RATING C

POTENTIAL IND NR? (Y or N) N

Contributing to a NR DISTRICT? C

Contributing secondary structure? NC

Listed on existing SURVEY? Local District; NR District



GENERAL INFORMATION

CATEGORY building HISTORIC FUNCTION Domestic - single dwelling
CONDITION good REASON for SIGNIFICANCE
INTEGRITY major alterations and/or addition(s)
SECONDARY STRUCTURE Detached garage

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Gable Front PLAN irregular
DETAILS NO OF STORIES 2
BEGINYEAR c. 1867 ROOF TYPE Multi-gable
OTHER YEAR ROOF MATERIAL Asphalt - shingle
DATESOURCE Plaque FOUNDATION Stone
WALL MATERIAL (current) Aluminum PORCH Front entry
WALL MATERIAL 2 (current) WINDOW MATERIAL Wood
WALL MATERIAL (original) Wood WINDOW MATERIAL Aluminum/vinyl
WALL MATERIAL 2 (original) WINDOW TYPE double hung/casement
WINDOW CONFIG 1/1; 4-light

SIGNIFICANT FEATURES Gable front portion of original house (first story only is original, with 2nd story an historic addition)

ALTERATIONS According to Sanborn Maps, house was originally a one-story structure that has been altered and added to over the years. SEE CONTINUATION SHEET.

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 135

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

According to Sanborn Maps, house was originally a one-story structure that has been altered and added to over the years: 1 story south side addition is historic, but south porch appears to have been altered (replacement posts, railing, and steps, Aluminum under eaves); second story addition to original house is historic; first story on north addition was added sometime between 1926 and 1949, with 2nd story added after; aluminum siding; replacement windows in altered openings (not historic--house originally had a full porch and entry on front façade); multiple rear additions; stone steps to north side entry and stone patio at front of house (not historic)

Post-2007 Alterations

Windows on front façade appear to be newer 1/1 aluminum replacement windows; porch railing replaced.

HISTORIC INFORMATION

HISTORIC NAME	Sporlein, Mary Elizabeth House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; low stone wall around lot; similar setbacks; mature trees
COA DATE	6/27/2016
COA DECISION	COA #16-2362 - In-kind replacement of front porch (approved 7/11/2016)

☒ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:	Porch structure does not appear to have been replaced, but porch railing is replacement.
------------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	



☒ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:	Replacement windows on front façade.
-----------------------	--------------------------------------

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	136
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818302002
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	Good local example of early 20th century Queen Anne.
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne Cottage	PLAN	irregular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1905	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Glass block
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; diamond/1

SIGNIFICANT FEATURES	Steep hipped roof with front and side gables; cornice returns; inset corner entry porch (altered).
----------------------	--

ALTERATIONS	Aluminum siding (not historic); porch has been downsized (see Sanborn maps), with replacement wrought iron supports/railings and concrete steps (not historic); rear porch addition; 2nd story rear addition; glass block in basement windows. Post-2007 -- 2/2 replacement windows on first story; replacement diamond/1 windows under front and south gables; replacement window in downsized opening under north gable; tilework on risers at front porch steps.
-------------	---

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS Sanborn maps (1909-1943) show a larger inset corner entry porch. See continuation sheet.

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION COA #18-2732 - In-kind replacement of windows (approved 7/17/2018)

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES: 2007 survey photos show 1/1 double-hung windows on front and side elevations -- replacement windows are 2/2.

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	142
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818302001
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1910	ROOF TYPE	Gable on hip
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Wrap around
WALL MATERIAL 2 (current)	Wood - shingle	WINDOW MATERIAL	Aluminum/vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	double hung
		WINDOW CONFIG	1/1
SIGNIFICANT FEATURES	Front gable roof; wraparound porch structure (roof); 2 story south side hipped roof bay		
ALTERATIONS	Replacement siding (not historic); decorative shutters (not historic); replacement windows in original openings (not-historic); replacement door (not historic); replacement supports/railing on porch (not historic); 3-sided 1st story south window bay addition (not historic); large 2 story rear/south addition (not historic); rear porch addition (not historic). Post-2007 -- solar panels installed on roof; front porch steps replaced.		

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO			
PERMITS			
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees		
COA DATE	6/28/2012		
COA DECISION	COA #12-2252 - Front steps replacement (approved 7/3/2012)		
☒ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☒ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

Solar panels on roof.

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	144
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818133002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	Solid example of Gable Front vernacular type.
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1890	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/fixed/single h
		WINDOW CONFIG	1/1; 2-light
SIGNIFICANT FEATURES	Front gable roof; 2 story south side gable bay with 1st story cutaway corners; historic 1/1 double and single hung windows		
ALTERATIONS	Full-front porch with solid knee walls and classical columns (c. 1910-15) ; replacement siding (historically appropriate); replacement front door (not historic); 2nd story projecting gable addition on north elevation (not historic); two story rear addition (not historic). Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO			
PERMITS			
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees		
COA DATE			
COA DECISION			
☐ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

--

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	145
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818130005
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Ranch	PLAN	irregular
DETAILS		NO OF STORIES	1
BEGINYEAR	c. 1950	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor/Sanborn Maps	FOUNDATION	Not visible
WALL MATERIAL (current)	Stone veneer	PORCH	Front entry
WALL MATERIAL 2 (current)	Aluminum	WINDOW MATERIAL	Vinyl
WALL MATERIAL (original)	Stone veneer	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Wood	WINDOW TYPE	Casement/fixe
		WINDOW CONFIG	Multi-light; 1-light
SIGNIFICANT FEATURES	Side gable roof with lower front gable bay at north end of front façade; stone veneer cladding; front entry porch with ornamental wrought iron support.		
ALTERATIONS	Aluminum awnings; replacement windows in original openings (not historic); aluminum under gables and eaves. Post-2007 -- In-kind asphalt shingle roof replacement in areas where small fire occurred		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; similar setbacks; mature trees
COA DATE	12/7/2018
COA DECISION	COA #18-4656 - In-kind shingle replacement in areas where small fire occurred (approved 12/10/2018)
☒ IN COMPLIANCE WITH COA?	
COA COMPLIANCE NOTES:	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS
SURVEYDATE	11/20/2025
SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

--

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	151
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818130004
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	IHSS (O); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	Although altered, this Queen Anne-style house remains an good example of the style within the district.
INTEGRITY	major alterations and/or addition(s)		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	1896	ROOF TYPE	Combination
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Front/side
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; multi-light
SIGNIFICANT FEATURES	Front bay w/ cutaway corners on 1st story and shingles/sunburst motif under gable; hipped main roof; flush north side gable; 1/1 windows on original house are historic (not original)		
ALTERATIONS	Recent renovation. Appropriate restoration work includes: replacement siding; replacement porch spindles and supports; replacement 1/1 windows; multi-light replacement windows on front bay; north entry porch--SEE CONTINUATION SHEET		

City of NAPERVILLE

ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 151

STREET N. ELLSWORTH STREET

ADDITIONAL PHOTOS OR INFORMATION

Alterations

Recent renovation. Appropriate restoration work includes: replacement siding; replacement porch spindles and supports; replacement 1/1 windows; multi-light replacement windows on front bay; north entry porch; 1 story rear addition. Inappropriate alterations include glass block basement windows and a large 2-story addition to the south, including entry and porch, which is difficult to distinguish from the original massing of the home.

Post-2007 Alterations

No changes.

HISTORIC INFORMATION

HISTORIC NAME	Schwartz, Charles
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	See IHSS photograph for appearance of house before renovation. Featured on p. 402 of A GUIDE TO CHICAGO'S HISTORIC SUBURBS.
PERMITS	
LANDSCAPE	Southwest corner of Ellsworth and School; front and north sidewalks; rear alley; similar setbacks; mature trees
COA DATE	
COA DECISION	
☐ IN COMPLIANCE WITH COA?	
COA COMPLIANCE NOTES:	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS
SURVEYDATE	11/20/2025
SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

--

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	152
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818133001
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	Despite alterations, this house remains a fine local example of the style.
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne	PLAN	irregular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1900	ROOF TYPE	Gable on hip
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	aluminum clad
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Glass block
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Front gable bay with 1st story cutaway corners; hipped two story north and south (altered) bays; square north window bay; classical wood lintels		
ALTERATIONS	Replacement front porch (appears to be appropriate); replacement windows in original openings (not historic) replacement siding; S. bay extended & S. porch added (not historic); 1 story rear add.; square N window bay add.; north gable window boarded up. Post-2007 -- no change.		

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southeast corner of School and Ellsworth; front and north sidewalks; picket fence; rear driveway; similar setbacks; mature trees
COA DATE	
COA DECISION	

☐ IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

--

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE
SURVEYAREA



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

--

\\images\\25_Ellsw
\\images\\25_Ellswo
\\images\\25_Ellswo
\\images\\25_Ellswo

STREET #	206
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132006
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	Good/fair	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	irregular
DETAILS	Italianate	NO OF STORIES	2
BEGINYEAR	c. 1870	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	Side Entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	2/2 vertical; 1/1; 6-light
SIGNIFICANT FEATURES	Front gable roof; historic 2/2 wood windows; square south two story window bay (early addition); N. side oval window		
ALTERATIONS	Aluminum siding; fixed shutters (not historic); original front entry replaced with window (historic); north entry & porch (not historic); replacement 6-light casement windows (historic); 2 story north addition (historic); south side porch extended (historic) & enclosed; 1 story rear addition (historic); rear exterior stair (not historic). Post-2007 - no changes.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE
Northeast corner of School and Ellsworth; front and south sidewalks; rear alley; rear wood fence; large north side yard

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\Images\\25_Ellsw

\\Images\\25_Ellswo

\\Images\\25_Ellswo

\\Images\\25_Ellswo

11/20/2025

NAPERVILLE HISTORIC DISTRICT

STREET #	214
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132005
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	Rare brick example of this vernacular type.
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	L-Form	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	1869	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Stone
WALL MATERIAL (current)	Brick	PORCH	Front
WALL MATERIAL 2 (current)	aluminum	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/storm
		WINDOW CONFIG	1/1; 1-light; 5-light

SIGNIFICANT FEATURES	Two story front gable bay with south side gable wing; segmental arch window openings with soldier course lintels, wide frieze board, concrete block entry porch addition with hipped roof, concrete block piers & knee walls, wood columns
----------------------	--

ALTERATIONS	Brick painted; two story rear addition; replacement porch (later enclosed--historic); replacement windows in slightly downsized openings; 2 story rear addition; door opening at first story of south wall on south wing (not historic); Aluminum frieze (not historic). Post-2007 -- no changes.
-------------	---

HISTORIC INFORMATION

HISTORIC NAME	Helm, Daniel House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATE	
COA DECISION	
☐ IN COMPLIANCE WITH COA?	
COA COMPLIANCE NOTES:	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS
SURVEYDATE	
SURVEYAREA	



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

--

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	215
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818129010
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	major alterations and/or addition(s)		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne (altered)	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1880	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Aluminum	PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	1/1; 1-light; fan light

SIGNIFICANT FEATURES	Front gable; south side gable with 1st story cutaway corners; recessed north side 2 story bay w/ 1st story cutaway corners; some historic 1/1 windows on original massing
----------------------	---

ALTERATIONS	Original house obscured by multiple alterations--aluminum siding; 1st story front entry addition (not historic); 2 story rear addition (not historic--abuts historic north side bay with 1st story cutaway corners); 1 story south/rear addition (historic--built between 1926 and 1943); wrought iron over entry; round front window (original front 1st story windows covered up); replacement window on 2nd story of north elevation; south side toward rear covered in stone veneer, wrought iron railing and floor-to-ceiling fixed windows & door on 2nd story of south side (toward rear). Post 2007 -- no changes.
-------------	--

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATE	
COA DECISION	

☐ IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

--

PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

--

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

11/20/2025

NAPERVILLE HISTORIC DISTRICT

STREET #	219
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818129009
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations		
SECONDARY STRUCTURE	detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Craftsman	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Aluminum	PORCH	Front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum/vinyl
WALL MATERIAL (original)	Unknown	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement/sto
		WINDOW CONFIG	1/1; 4-light; 1-light

SIGNIFICANT FEATURES	Broad front gable roof; front gable porch with brick knee walls (enclosed);
----------------------	---

ALTERATIONS	Aluminum siding; rear/south entry and porch addition; 2 story rear addition. Post-2007 – Aluminum siding repainted or replaced; 4-light geometric wood windows in enclosed porch relaced with single-light Aluminum windows; door to enclosed porch replaced; 1/1 Aluminum replacement windows in existing openings on front and side elevations; south-side entry porch removed; replacement door in south-side ground-level entry; cast stone covering base of front porch and foundation.
-------------	--

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees
COA DATE	10/22/2020
COA DECISION	COA #20-3281 - Made change without COA from brick to Bristol stone cast on the primary façade (denied by HPC on 10/22/20 and appeal denied by CC on 12/15/20)

☐ IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

Cast stone not removed.

PREPARER Lara Ramsey
PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE
SURVEYAREA



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

Replacement windows throughout; south side entry porch removed; replacement door in ground-level south-side entry.

\\images\25_Ellsw
\\images\25_Ellswo
\\images\25_Ellswo
\\images\25_Ellswo

STREET #	220
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132004
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Bungalow	PLAN	rectangular
DETAILS	Tudor Revival	NO OF STORIES	1.5
BEGINYEAR	c. 1930	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Glass block
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/casement
		WINDOW CONFIG	6/6; 8/8; 6-light

SIGNIFICANT FEATURES	Front gable roof with one story front gable bay; inset front entry porch with square brick corner column at south end of bay.
----------------------	---

ALTERATIONS	Replacement windows in original openings (not historic); 3-sided window bay addition on south side (not historic). Post-2007 -- no changes.
-------------	---

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear fence

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\\25_Ellsw

\\images\\25_Ellswo

\\images\\25_Ellswo

\\images\\25_Ellswo

STREET #	223
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818129008
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	S
Listed on existing SURVEY?	Local District; NR District; NH

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	Fine, intact example of early 20th-century Queen Anne - Free Classic style.
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	Carriage house		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGIN YEAR	1908	ROOF TYPE	Gable on hip
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATE SOURCE	Plaque	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum clad
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Wood
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 2-light
SIGNIFICANT FEATURES	Gable on hip roof; full front porch with rounded columns; 2 story north 3-sided bay with pent gable roof; north hipped dormer; historic wood cladding; windows on front façade and first story of north elevation at east end appear to be historic wood windows.		
ALTERATIONS	Replacement windows on sections of north elevation and south elevation (not historic -- appropriate configuration); 1 story rear addition (1999). Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME	Patterson, William Henry House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	McCorkel, Frank
ARCHITECT SOURCE	
HISTORIC INFO	Patterson, a farmer in Wheatland Township, had the home built after his retirement.
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear driveway; similar setbacks; mature trees; rear wood fencing
COA DATE	
COA DECISION	
☐ IN COMPLIANCE WITH COA?	
COA COMPLIANCE NOTES:	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS
SURVEYDATE	11/20/2025
SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

--

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	224
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132003
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gabled Ell	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1900	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Wrap around
WALL MATERIAL 2 (current)	Wood - shingle	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Aluminum/vinyl
WALL MATERIAL 2 (original)	Wood - shingle	WINDOW TYPE	double hung; fixed
		WINDOW CONFIG	1/1; 9/9; multi-light

SIGNIFICANT FEATURES	Two story front gable bay and south side ell; historic 1/1 wood windows on first story.
----------------------	---

ALTERATIONS	Wrap around front porch with new concrete blk piers(not historic); replacement windows in original openings on 2nd story (not historic); replacement siding; stained glass replacement window on north side and under front gable; 1 story rear porch addition. Post-2007 -- metal handrail at steps to front porch.
-------------	--

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO			
PERMITS			
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees		
COA DATE			
COA DECISION			
☐ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☒ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

Metal handrail added to steps on front porch.

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET # 229
DIRECTION N
STREET ELLSWORTH
SUFFIX ST
PIN 0818129007

LOCAL SIGNIFICANCE RATING C

POTENTIAL IND NR? (Y or N) N

Contributing to a NR DISTRICT? C

Contributing secondary structure? -

Listed on existing SURVEY? Local District; NR District



GENERAL INFORMATION

CATEGORY building HISTORIC FUNCTION Domestic - single dwelling
CONDITION good REASON for SIGNIFICANCE
INTEGRITY major alterations and/or addition(s)
SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Gable Front PLAN rectangular
DETAILS NO OF STORIES 2
BEGINYEAR 1873 ROOF TYPE Front gable
OTHER YEAR ROOF MATERIAL Asphalt - shingle
DATESOURCE surveyor/tax records FOUNDATION Stone
WALL MATERIAL (current) Aluminum PORCH Side
WALL MATERIAL 2 (current) WINDOW MATERIAL Wood
WALL MATERIAL (original) Wood WINDOW MATERIAL Aluminum/vinyl
WALL MATERIAL 2 (original) WINDOW TYPE double hung
WINDOW CONFIG 2/2 vertical; 1/1

SIGNIFICANT FEATURES Front gable roof and rectangular massing; 2/2 vertical wood windows (lintels covered with aluminum, but are historic); frieze board

ALTERATIONS Appears that front entry was covered up, & new side entry & porch built (post 1949); 2 story rear add. (historic); south add. (post 1949); exterior stair w/ 2nd story S. window converted to door (not historic); aluminum siding. Post-2007 - 1/1 vinyl replacement windows at second story of south end of front façade and at west end of north elevation at first story; Aluminum siding replaced or repainted; non-historic fixed shutters evident in 2007 have been removed; in-kind asphalt shingle roof replacement.

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO	Tax records research by Naperville Heritage Society indicate that house was probably built around 1873.		
PERMITS	Sanborn maps through 1949 show house with entry at front and no side porch.		
LANDSCAPE	Southwest corner of Ellsworth and North; front and north sidewalks; south side yard; rear driveway; mature trees		
COA DATE	11/14/2017		
COA DECISION	COA #17-4764 - In-kind replacement of asphalt shingles (approved 11/14/2017)		
☒ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☒ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK: 1/1 vinyl replacement windows in select openings on front façade and north elevation; non-historic fixed shutters removed.

\\Images\\25_Ellsw

\\Images\\25_Ellswo

\\Images\\25_Ellswo

\\Images\\25_Ellswo

STREET #	230
DIRECTION	N
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818132001
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1915	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)	Stucco	WINDOW MATERIAL	Wood/vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	beveled glass
WALL MATERIAL 2 (original)	Stucco	WINDOW TYPE	Double hung/casement/fix
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves and front hipped dormer; full front porch with round columns on concrete block piers; 1st story north square window bay w/ beveled glass casement windows; beveled glass windows under porch; 3-sided S. window bay		
ALTERATIONS	1/1 replacement windows in original openings (not historic); replacement railing and added frieze on porch. Post-2007 -- single window at north end of front façade under porch replaced with paired Aluminum/vinyl 1/1 double-hung windows; replacement asphalt shingle roofing.		

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO			
PERMITS			
LANDSCAPE	Southeast corner of North and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees		
COA DATE	11/23/2016		
COA DECISION	COA #16-4595 - In-kind shingle replacement (approved 11/28/2016)		
☒ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☒ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

single window at north end of front façade under porch replaced with paired Aluminum/vinyl 1/1 double-hung windows.

\\images\\25_Ellsw

\\images\\25_Ellswo

\\images\\25_Ellswo

STREET #	4-6
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314001
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	IHSS (O); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Commerce/Trade
CONDITION	good	REASON for SIGNIFICANCE	The only commercial block in the historic district, this 19th-century building still retains much of its historic character.
INTEGRITY	minor alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Two Part Commercial Block	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1864	ROOF TYPE	Flat
OTHER YEAR		ROOF MATERIAL	Not visible
DATESOURCE	Owner (2007 survey)	FOUNDATION	Stone
WALL MATERIAL (current)	Brick	PORCH	-
WALL MATERIAL 2 (current)	Stucco	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Vinyl/glass block
WALL MATERIAL 2 (original)	wood shingle	WINDOW TYPE	Storefront/double hung
		WINDOW CONFIG	1-light; 1/1
SIGNIFICANT FEATURES	Dentil cornice; northwest corner entry w/ 2nd story rounded turret with wood shingles; cast iron columns at entry; stone segmental arch label molds on window openings w/ rough stone sills		
ALTERATIONS	Brick painted; original conical roof atop round northwest corner tower removed; display windows and storefront door are replacement, but may be historic; concrete steps and railing; replacement upper windows in original openings; glass block windows in basement openings. Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO
Historic photograph of building on p. 37 of NAPERVILLE HOMECOMING (1917). Sanborn maps from as early as 1898 list building being used as a sausage factory.

PERMITS

LANDSCAPE
Southeast corner of Ellsworth and Benton; front and north sidewalks; building comes to sidewalk; street parking; attached to building at 8 S. Ellsworth on S side

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\\25_Ellsw

\\images\\25_Ellswo

\\images\\25_Ellswo

\\images\\25_Ellswo

STREET #	8
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314001
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	Rare example of the I-House in the district.
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	I-House	PLAN	rectangular
DETAILS	Italianate	NO OF STORIES	2
BEGINYEAR	c. 1870	ROOF TYPE	Side gable
OTHER YEAR	c. 1905	ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Owner/Sanborn Maps	FOUNDATION	Stone
WALL MATERIAL (current)	Brick	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	Aluminum/vinyl
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1
SIGNIFICANT FEATURES	Side gable roof and rectangular massing; symmetrical front façade with center entry; segmental arch and rectangular window openings with stone label molds on front façade and brick lintels on side; with rusticated stone sills		
ALTERATIONS	Aluminum siding under eaves; painted brick; 2 story S & rear add. (c. 1905); replacement windows in original openings (historic); front entry door & sidelights (c. 1905); replacement front porch (c. 1905); 1 story rear add. (post-1943). Post-2007 -- Aluminum/vinyl 1/1 replacement windows on first story of front façade.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO
Owner indicated that the building was originally an ice house that was attached to 4-6 S. Ellsworth.

PERMITS
Sanborn Maps indicate that original 2 story building was extended south and east between 1898 and 1909--front porch, windows, and entry probably date from that time.

LANDSCAPE
Midblock on east side of residential street; attached to 4-6 S. Ellsworth on N. side; front sidewalk; rear alley; front planting

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



☒ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

Aluminum/vinyl 1/1 replacement windows on first story of front façade.

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

11/20/2025

NAPERVILLE HISTORIC DISTRICT

STREET #	12
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - multiple dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	L-Form	PLAN	L
DETAILS	Greek Revival	NO OF STORIES	2
BEGINYEAR	c. 1870	ROOF TYPE	Multi-gable
OTHER YEAR	c. 1910	ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Aluminum	PORCH	Full front
WALL MATERIAL 2 (current)	wood - vertical board	WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	6/6; 6/9

SIGNIFICANT FEATURES	Two story front gable bay with intersecting south side gable wing; historic replacement front porch (c. 1910)
----------------------	---

ALTERATIONS	Aluminum and vertical wood siding (not historic); wood replacement windows in original openings (openings may have been altered on 1st story under porch, historic); north end door under porch added, and replacement door at south end entry (may be historic alteration); fixed shutters (not historic); 2 story rear addition with exterior stair (not historic). Post-2007 --6/6 Aluminum/vinyl replacement windows in existing openings on second story; end chimney on south elevation demolished.
-------------	---

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO	Building does not appear on 1869 Bird's Eye View of Naperville, but is present on the 1886 Sanborn Map. Sanborn maps also indicate that the full-front porch was constructed sometime between 1909 and 1921.		
PERMITS			
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees		
COA DATE			
COA DECISION			
☐ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	



☒ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

Aluminum/vinyl replacement windows on 2nd story; chimney on south elevation demolished.

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET # 16
 DIRECTION S
 STREET ELLSWORTH
 SUFFIX ST
 PIN 0818314003

LOCAL SIGNIFICANCE RATING S

POTENTIAL IND NR? (Y or N) N

Contributing to a NR DISTRICT? C

Contributing secondary structure? -

Listed on existing SURVEY? IHSS (O); Local District; NR



GENERAL INFORMATION

CATEGORY building HISTORIC FUNCTION Domestic - multiple dwelling
 CONDITION excellent REASON for SIGNIFICANCE Excellent example of Italianate residential architecture in the district. Front porch is historic, and dates from the 1910s.
 INTEGRITY minor alterations and addition(s)
 SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Duplex-Italianate PLAN rectangular
 DETAILS NO OF STORIES 2
 BEGIN YEAR c. 1870 ROOF TYPE Hipped
 OTHER YEAR c. 1925 ROOF MATERIAL Asphalt - shingle
 DATE SOURCE Surveyor FOUNDATION Concrete - block
 WALL MATERIAL (current) Wood PORCH Full front
 WALL MATERIAL 2 (current) WINDOW MATERIAL wood
 WALL MATERIAL (original) Wood WINDOW MATERIAL Aluminum/vinyl
 WALL MATERIAL 2 (original) WINDOW TYPE double hung
 WINDOW CONFIG 1/1; 2/2 vert.

SIGNIFICANT FEATURES Shallow hipped roof; historic 2/2 vertical wood windows on 1st story; label molds on all window openings; wide wood frieze under eaves; historic replacement front porch (c. 1910)

ALTERATIONS Vinyl replacement windows in original openings on 2nd story (not historic); 2 story rear addition w/ 2nd story deck (not historic); replacement front doors; fixed shutters; 1 story rear/south addition (post-1954). Post-2007 -- no changes.

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps indicate that the building was converted into a duplex sometime between 1921 and 1926.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; large south side yard; mature trees

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

SURVEYDATE

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\\25_Ellsw

\\images\\25_Ellswo

\\images\\25_Ellswo

\\images\\25_Ellswo

STREET #	20
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314004
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

GENERAL INFORMATION

CATEGORY	site	HISTORIC FUNCTION	Landscape - unoccupied land
CONDITION		REASON for SIGNIFICANCE	
INTEGRITY			
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Vacant Lot	PLAN	
DETAILS		NO OF STORIES	
BEGINYEAR		ROOF TYPE	
OTHER YEAR		ROOF MATERIAL	
DATESOURCE		FOUNDATION	
WALL MATERIAL (current)		PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	
WALL MATERIAL (original)		WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	
		WINDOW CONFIG	
SIGNIFICANT FEATURES			
ALTERATIONS			

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA

\\images\\ellsworth

\\images\\ellsworth0

\\images\\ellsworth0

\\images\\ellsworth0

STREET #	22
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314005
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	IHSS (P); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	Handsome Italianate with exuberant detailing at windows and entry. Listed on IHSS (P).
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1875	ROOF TYPE	Front gable
OTHER YEAR	c. 1910	ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor/Chain of Title	FOUNDATION	Stone/concrete block
WALL MATERIAL (current)	Wood	PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	2/2; 6/6; 1/1
SIGNIFICANT FEATURES	Front gable roof w/ wood frieze; historic 2/2 & 6/6 wood windows; elaborate flat arch wood frames and lintels w/ keystones & rope molding on façade; segmental arch wood crowns over windows on side elevations; flattened arch entry transom & wood lintel		
ALTERATIONS	Full front porch addition (c. 1910); 1/1 replacement windows in downsized openings on north elevation (not historic, toward rear); two side entry doors on south segmental arch bay (not historic), with wood deck; replacement front door. Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME	Metz, Adam House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	Chain of title indicates Metz purchased property from Alvin Scott in 1874 for \$440. Inventory of Metz estate date 1878 makes mention of house.
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; rear and side picket fence; large south side yard; mature trees
COA DATE	
COA DECISION	
☐ IN COMPLIANCE WITH COA?	
COA COMPLIANCE NOTES:	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS
SURVEYDATE	
SURVEYAREA	



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

--

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	30
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818314006
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	N/A
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Neo-Traditional	PLAN	L
DETAILS		NO OF STORIES	2.5
BEGINYEAR	2012	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Standing seam metal
DATESOURCE	COA	FOUNDATION	Concrete
WALL MATERIAL (current)	Fiber Cement Board	PORCH	Wrap around
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum/vinyl
WALL MATERIAL (original)	-	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Casement/fixed
		WINDOW CONFIG	2-light; 4-light
SIGNIFICANT FEATURES			
ALTERATIONS			

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	Former site of late 19th century Greek Revival residence.
PERMITS	
LANDSCAPE	Northeast corner of S. Ellsworth and Van Buren; front and south sidewalks; rear/south picket fence; rear alley; oversize lot; mature trees
COA DATE	5/6/2016; 1/26/2012
COA DECISION	COA #15-3111 - Addition of 2 upper story windows, modifying screen porch to windows (approved 3/28/2016); COA #11-2993 - demolition of the existing structure and new construction (approved by HPC 1/26/2012); COA #13-3320 - Modifications to the site plan and Building Elevations approved through COA #11-2293 (approved by HPC 9/26/2013); COA #15-3111 - construction of new residence (tabled by HPC 9/24/2015, approved
☒ IN COMPLIANCE WITH COA?	
COA COMPLIANCE NOTES:	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS
SURVEYDATE	
SURVEYAREA	



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

--

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

STREET #	104
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319001
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	S
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	Quintessential example of Free Classic Queen Anne from around the turn of the 20th century.
INTEGRITY	major alterations and/or addition(s)		
SECONDARY STRUCTURE	Barn		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Queen Anne - Free Classic	PLAN	irregular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1905	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Hipped main roof; front & south 2-story pent gable bays; full front porch with Ionic columns on wood knee wall; historic 1/1 wood windows with simple wood surrounds topped by classical crowns		
ALTERATIONS	Fixed front window is replacement (possibly historic); replacement porch steps (not historic); rear deck addition (not historic). Post-2007 -- decorative tiles on risers of porch steps.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southeast corner of Van Buren and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\Images\\25_Ellsw

\\Images\\25_Ellswo

\\Images\\25_Ellswo

\\Images\\25_Ellswo

STREET #	110
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Minimal Traditional	PLAN	rectangular
DETAILS		NO OF STORIES	1.5
BEGINYEAR	c. 1950	ROOF TYPE	Side gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor/Sanborn Map	FOUNDATION	Concrete
WALL MATERIAL (current)	Wood	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Aluminum
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1
SIGNIFICANT FEATURES	Side gable roof with front gable bay and dormer; front entry porch (altered)		
ALTERATIONS	Wrought iron railings on front porch (may be original); fixed shutters; Aluminum under eaves. Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps indicate that the house was constructed sometime between 1949 and 1954.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; similar setbacks; mature trees

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☒ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

1/1 replacement windows on attic level and in front dormer.

\\Images\\25_Ellsw

\\Images\\25_Ellswo

\\Images\\25_Ellswo

\\Images\\25_Ellswo

STREET #	114
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319003
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	NC
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	American Foursquare	PLAN	Rectangular
DETAILS	Prairie	NO OF STORIES	2.5
BEGINYEAR	c. 1925	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung/casement/aw
		WINDOW CONFIG	4/1; 3-light; 9-light geo.
SIGNIFICANT FEATURES	Hipped roof with overhanging eaves; 1 story front bay w/ 9-light geometric wood windows on south end of facade; historic wood windows		
ALTERATIONS	Aluminum under eaves; front entry porch at north end of front façade enclosed, center entry porch added (post 1954); replacement front steps and railing (not historic); rear deck addition (not historic). Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO
Aerial photographs indicate that the center entry porch was constructed sometime between 1978 and 1987.

PERMITS

LANDSCAPE
Midblock on east side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo

11/20/2025

NAPERVILLE HISTORIC DISTRICT

STREET # 120
 DIRECTION S
 STREET ELLSWORTH
 SUFFIX ST
 PIN 0818319004

LOCAL SIGNIFICANCE RATING S

POTENTIAL IND NR? (Y or N) N

Contributing to a NR DISTRICT? C

Contributing secondary structure? C

Listed on existing SURVEY? IHSS (O); Local District; NR



GENERAL INFORMATION

CATEGORY building HISTORIC FUNCTION Domestic - single dwelling
 CONDITION good REASON for SIGNIFICANCE Even with the front porch addition and rear additions, this house remains local example of the Queen Anne style.
 INTEGRITY minor alterations and addition(s)
 SECONDARY STRUCTURE Detached garage

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Queen Anne
 DETAILS
 BEGINYEAR c. 1880
 OTHER YEAR
 DATESOURCE surveyor
 WALL MATERIAL (current) Wood
 WALL MATERIAL 2 (current) wood - shingle
 WALL MATERIAL (original) Wood
 WALL MATERIAL 2 (original) Wood - shingle
 PLAN irregular
 NO OF STORIES 2
 ROOF TYPE Front gable
 ROOF MATERIAL Asphalt - shingle
 FOUNDATION Stone
 PORCH Front entry
 WINDOW MATERIAL Wood
 WINDOW MATERIAL Aluminum
 WINDOW TYPE Double hung/fixed/caseme
 WINDOW CONFIG 1/1; 1-light

SIGNIFICANT FEATURES Front gable bay with cutaway corners; scrolled brackets; hipped 2 story south entry bay; 2 story south side gable bay; historic 1/1 wood windows

ALTERATIONS One story north/rear addition; rear deck addition (not historic); casement & fixed windows appear to be replacement, but may be historic; north chimney addition (not historic); front entry porch addition (post-1954). Post-2007 -- 1/1 Aluminum replacement windows at 2nd story of front bay

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps indicate the house originally featured a two-story north wing with a one-story west-facing porch, which was removed sometime between 1921 and 1926.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE 5/18/2018

COA DECISION COA #18-1902 - In-kind replacement of windows (approved 5/23/2018)

☒ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\Images\\25_Ellsw

\\Images\\25_Ellswo

\\Images\\25_Ellswo

\\Images\\25_Ellswo

11/20/2025

NAPERVILLE HISTORIC DISTRICT

STREET #	126
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319005
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	IHSS (O); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	Handsome 1870s Italianate, with many historic features.
INTEGRITY	minor alterations		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Italianate	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	1873	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Owner's research (2007 survey)	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	2/2 vertical
SIGNIFICANT FEATURES	Front gable roof with wide wood frieze; south polygonal window bay with segmental arch windows, narrow round arch wood panels, carved brackets, and paneled frieze; 2/2 wood windows with flanged pediment lintels; recessed entry with paneled sides & transoms; historic double wood doors (altered)		
ALTERATIONS	Solid arched glass panes in front doors were probably originally wood (not historic); replacement front and south/rear porches (historic); concrete front steps with wrought iron railing; 1 story north/rear addition (historic). Post-2007 -- replacement asphalt-shingle roof.		

HISTORIC INFORMATION

HISTORIC NAME	Stenger, Elizabeth
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	History provided by owner during 2007 survey.
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATE	4/19/2020
COA DECISION	COA #20-831 - In-kind shingle replacement (approved 4/23/2020)
☒ IN COMPLIANCE WITH COA?	
COA COMPLIANCE NOTES:	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS
SURVEYDATE	11/20/2025
SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

--

\\images\25_Ellsw
\\images\25_Ellswo
\\images\25_Ellswo
\\images\25_Ellswo

STREET #	130
DIRECTION	S
STREET	ELLSWORTH
SUFFIX	ST
PIN	0818319006
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	not altered		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Minimal Traditional	PLAN	L
DETAILS		NO OF STORIES	1
BEGINYEAR	1953-54	ROOF TYPE	Hipped
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Owner	FOUNDATION	Not visible
WALL MATERIAL (current)	Stone veneer	PORCH	Front entry
WALL MATERIAL 2 (current)	Brick	WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Stone veneer	WINDOW MATERIAL	Glass block
WALL MATERIAL 2 (original)	Brick	WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	2/2; 2/3; multi-light
SIGNIFICANT FEATURES	Stone veneer on façade; hipped roof with overhanging eaves; rounded corner entry; historic double hung & multi-light wood windows; 3-sided front window bay; glass block beside entry		
ALTERATIONS	Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Ellsw

\\images\25_Ellswo

\\images\25_Ellswo

\\images\25_Ellswo