

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** 1892 Sanborn Map shows no front porch; 1898 map shows front entry porch. Current porch has no entry/steps. [from A GUIDE TO CHICAGO'S HISTORIC SUBURBS, p. 401]

"This clapboard farmhouse, built in 1874, has the massing and details reminiscent of Greek Revival, but with pedimented window heads characteristic of the 1870s date. Added at the turn of the century was the porch with its four, standard, Tuscan columns. The west end of the building

**PERMITS**

**LANDSCAPE** Northwest corner of Franklin and Ellsworth; front and south sidewalks; side driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; side driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** House history questionnaire submitted by owner includes chain of title/ownership information and tax records. Title research indicates that the property was owned by Samuel Barr at the time the house was constructed.

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE** 8/20/2018;4/26/2019

**COA DECISION** COA #18-3335 - Replacing door with window and in-kind replacement matching existing window (approved 8/22/2018); COA #19-1196 - remove window replace with door - door existed prior to 2018 (approved 4/26/2019)

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER** Lara Ramsey

**SURVEYDATE**

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:** All work listed in alterations with the exception of the replacement front door in north end entry under porch

11/20/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

**SIGNIFICANT FEATURES** Front gable portion is original house (windows on first story appear historic); round arch window openings w/ center keystones; half round window under gable; round arch front entry; historic two-story south/rear addition constructed in 1903 (addition originally featured a second west-facing porch)

**ALTERATIONS** Paired brackets & dentils appear to be later (may be restoration); replacement windows on 2nd story or original structure (not historic); replacement door & transom (not historic); large 2 story S. side addition w/ corner tower (not historic--1990s); replacement porch (not historic-1990s); 1 story north bay addition (not historic); segmental arch window on 2nd story north elevation (not historic); chimney (not historic); rear screened porch addition (not historic). Post-2007 -- no changes.

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** According to history of the house in Naperville Heritage Society address file, the house was built in 1872. See IHSS photograph for original massing of house. According to A GUIDE TO CHICAGO'S HISTORIC SUBURBS (p. 401-2), the south/rear addition was constructed in 1903 and featured a west-facing porch. The porch was removed when the large 2-story addition with corner tower was constructed in the 1990s.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; parking lot to south; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

IN COMPLIANCE WITH COA?

**COA COMPLIANCE NOTES:**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYDATE**

**SURVEYAREA**



ELIGIBLE WORK COMPLETED WITHOUT COA?

**NOTES ON WORK:**

11/20/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fence

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**SURVEYDATE**

**PREPARER ORGANIZATION**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:** 6/1 vinyl replacement windows in existing openings; replacement front door; aluminum siding around first story windows at west end of south elevation replaced.

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 135

STREET N. ELLSWORTH STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Alterations*

According to Sanborn Maps, house was originally a one-story structure that has been altered and added to over the years: 1 story south side addition is historic, but south porch appears to have been altered (replacement posts, railing, and steps, Aluminum under eaves); second story addition to original house is historic; first story on north addition was added sometime between 1926 and 1949, with 2<sup>nd</sup> story added after; aluminum siding; replacement windows in altered openings (not historic--house originally had a full porch and entry on front façade); multiple rear additions; stone steps to north side entry and stone patio at front of house (not historic)

#### *Post-2007 Alterations*

Windows on front façade appear to be newer 1/1 aluminum replacement windows; porch railing replaced.

**HISTORIC INFORMATION**

**HISTORIC NAME** Sporlein, Mary Elizabeth House

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; low stone wall around lot; similar setbacks; mature trees

**COA DATE** 6/27/2016

**COA DECISION** COA #16-2362 - In-kind replacement of front porch (approved 7/11/2016)

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:** Porch structure does not appear to have been replaced, but porch railing is replacement.

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYDATE** 11/20/2025

**SURVEYAREA** NAPERVILLE HISTORIC DISTRICT



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:** Replacement windows on front façade.

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS** Sanborn maps (1909-1943) show a larger inset corner entry porch. See continuation sheet.

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE** 7/10/2018

**COA DECISION** COA #18-2732 - In-kind replacement of windows (approved 7/17/2018)

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:** 2007 survey photos show 1/1 double-hung windows on front and side elevations -- replacement windows are 2/2.

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

11/20/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; similar setbacks; mature trees

**COA DATE**

**COA DECISION** COA #18-4656 - In-kind shingle replacement in areas where small fire occurred (approved 12/10/2018)

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**City of NAPERVILLE**  
ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

**STREET #** 151

**STREET** N. ELLSWORTH STREET

---

**ADDITIONAL PHOTOS OR INFORMATION**

*Alterations*

Recent renovation. Appropriate restoration work includes: replacement siding; replacement porch spindles and supports; replacement 1/1 windows; multi-light replacement windows on front bay; north entry porch; 1 story rear addition. Inappropriate alterations include glass block basement windows and a large 2-story addition to the south, including entry and porch, which is difficult to distinguish from the original massing of the home.

*Post-2007 Alterations*

No changes.

**HISTORIC INFORMATION**

**HISTORIC NAME** Schwartz, Charles

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** See IHSS photograph for appearance of house before renovation. Featured on p. 402 of A GUIDE TO CHICAGO'S HISTORIC SUBURBS.

**PERMITS**

**LANDSCAPE** Southwest corner of Ellsworth and School; front and north sidewalks; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

IN COMPLIANCE WITH COA?

**COA COMPLIANCE NOTES:**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYDATE**

**SURVEYAREA**



ELIGIBLE WORK COMPLETED WITHOUT COA?

**NOTES ON WORK:**

11/20/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of School and Ellsworth; front and north sidewalks; picket fence; rear driveway; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

IN COMPLIANCE WITH COA?

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



ELIGIBLE WORK COMPLETED WITHOUT COA?

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Northeast corner of School and Ellsworth; front and south sidewalks; rear alley; rear wood fence; large north side yard

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME** Helm, Daniel House

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER** Lara Ramsey

**SURVEYDATE**

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

11/20/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on west side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees

**COA DATE** 10/22/2020

**COA DECISION** COA #20-3281 - Made change without COA from brick to Bristol stone cast on the primary façade (denied by HPC on 10/22/20 and appeal denied by CC on 12/15/20)

IN COMPLIANCE WITH COA?

**COA COMPLIANCE NOTES:** Cast stone not removed.

**PREPARER ORGANIZATION** Lara Ramsey  
RAMSEY HISTORIC CONSULTANTS

**SURVEYDATE** 11/20/2025  
**SURVEYAREA** NAPERVILLE HISTORIC DISTRICT



ELIGIBLE WORK COMPLETED WITHOUT COA?

**NOTES ON WORK:** Replacement windows throughout; south side entry porch removed; replacement door in ground-level south-side entry.

\\images\25\_Ellsw  
\\images\25\_Ellswo  
\\images\25\_Ellswo  
\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear fence

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**SURVEYDATE**

**PREPARER ORGANIZATION**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Tax records research by Naperville Heritage Society indicate that house was probably built around 1873.

**PERMITS** Sanborn maps through 1949 show house with entry at front and no side porch.

**LANDSCAPE** Southwest corner of Ellsworth and North; front and north sidewalks; south side yard; rear driveway; mature trees

**COA DATE** 11/14/2017

**COA DECISION** COA #17-4764 - In-kind replacement of asphalt shingles (approved 11/14/2017)

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYDATE** 11/20/2025

**SURVEYAREA** NAPERVILLE HISTORIC DISTRICT



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:** 1/1 vinyl replacement windows in select openings on front façade and north elevation; non-historic fixed shutters removed.

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of North and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION** COA #16-4595 - In-kind shingle replacement (approved 11/28/2016)

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:** single window at north end of front façade under porch replaced with paired Aluminum/vinyl 1/1 double-hung windows.

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**


**LANDSCAPE**

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

**PREPARER**

**SURVEYDATE**

**PREPARER ORGANIZATION**

**SURVEYAREA**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

**PREPARER**

**SURVEYDATE**

**PREPARER ORGANIZATION**

**SURVEYAREA**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Building does not appear on 1869 Bird's Eye View of Naperville, but is present on the 1886 Sanborn Map. Sanborn maps also indicate that the full-front porch was constructed sometime between 1909 and 1921.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:** Aluminum/vinyl replacement windows on 2nd story; chimney on south elevation demolished.

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Sanborn maps indicate that the building was converted into a duplex sometime between 1921 and 1926.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; large south side yard; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

**PREPARER**

**SURVEYDATE**

**PREPARER ORGANIZATION**

**SURVEYAREA**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN


LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION

INTEGRITY

REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Side yard associated with 16 S. Ellsworth Street.

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

**PREPARER**

**SURVEYDATE**

**PREPARER ORGANIZATION**

**SURVEYAREA**

\\images\ellsworth

\\images\ellsworth0

\\images\ellsworth0

\\images\ellsworth0

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**HISTORIC INFORMATION**

**HISTORIC NAME** Metz, Adam House

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Chain of title indicates Metz purchased property from Alvin Scott in 1874 for \$440. Inventory of Metz estate date 1878 makes mention of house.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear and side picket fence; large south side yard; mature trees

**COA DATE**

**COA DECISION**

IN COMPLIANCE WITH COA?

**COA COMPLIANCE NOTES:**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYDATE**

**SURVEYAREA**



ELIGIBLE WORK COMPLETED WITHOUT COA?

**NOTES ON WORK:**

11/20/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Former site of late 19th century Greek Revival residence.

**PERMITS**

**LANDSCAPE** Northeast corner of S. Ellsworth and Van Buren; front and south sidewalks; rear/south picket fence; rear alley; oversize lot, mature trees

**COA DATE** 5/6/2016; 1/26/2012

**COA DECISION** COA #15-3111 - Addition of 2 upper story windows, modifying screen porch to windows (approved 3/28/2016); COA #11-2993 - demolition of the existing structure and new construction (approved by HPC 1/26/2012); COA #13-3320 - Modifications to the site plan and Building Elevations approved through COA #11-2293 (approved by HPC 9/26/2013); COA #15-3111 - construction of new residence (tabled by HPC 9/24/2015, approved

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw  
 \\images\25\_Ellsw  
 \\images\25\_Ellsw  
 \\images\25\_Ellsw

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Van Buren and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Sanborn maps indicate that the house was constructed sometime between 1949 and 1954.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:** 1/1 replacement windows on attic level and in front dormer.

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Aerial photographs indicate that the center entry porch was constructed sometime between 1978 and 1987.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Sanborn maps indicate the house originally featured a two-story north wing with a one-story west-facing porch, which was removed sometime between 1921 and 1926.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE** 5/18/2018

**COA DECISION** COA #18-1902 - In-kind replacement of windows (approved 5/23/2018)

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYDATE**

**SURVEYAREA**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

11/20/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**HISTORIC INFORMATION**

**HISTORIC NAME** Stenger, Elizabeth

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS** History provided by owner during 2007 survey.

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATE** 4/19/2020

**COA DECISION** COA #20-831 - In-kind shingle replacement (approved 4/23/2020)

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYDATE** 11/20/2025

**SURVEYAREA** NAPERVILLE HISTORIC DISTRICT



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**IN COMPLIANCE WITH COA?**

**COA COMPLIANCE NOTES:**



**ELIGIBLE WORK COMPLETED WITHOUT COA?**

**NOTES ON WORK:**

**PREPARER**

**SURVEYDATE**

**PREPARER ORGANIZATION**

**SURVEYAREA**

\\images\25\_Ellsw

\\images\25\_Ellswo

\\images\25\_Ellswo

\\images\25\_Ellswo