

88

Pipe Material



- Polyvinyl Chloride
- Vitrified Clay Pipe
- CIPP
- Ductile Iron Pipe
- Reinforced Concrete Pipe
- Not Known

2 / 2

CCTV Progress

35.86 mi

televised

23.71 mi


12.15 mi

Contractor

City

Annual Goal: 69.68% complete

1 / 2



Defects Identified

1,322

Legend

Defects Summary

GNETO Observations

Defects

- Broken
- Collapse
- Crack/Fracture
- Deposit
- Hole
- Infiltration
- Intruding Sealing Ring
- Intruding Tap
- Joint Offset/Separated
- Liner Defect
- Obstruction
- Root Ball
- Root