

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO According to NHS Walking Tour-East brochure (p. 5), Germann was a tailor who came to America in 1851. Photograph from the 1970s included in the IHSS, which shows the house with its original wood windows and massing.

PERMITS 1898 Sanborn map (sheet 2) shows house without front porch.

LANDSCAPE Northwest corner of Sleight and Benton; front and south sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION COA #09-2343 - Window replacement (approved 8/12/2009); COA #10-2529 (8/28/2010) - In-kind replacement of the bay window and two 2nd floor windows on the south façade with aluminum clad wood windows. (approved 9/2/2010); COA #12-3270 - front door replacement (approved 9/13/2012); COA 19-3324 (9/27/2019) -- two story rear addition (approved 9/26/2019 and issued 9/27/2019).

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS Sanborn maps show changes in the footprint of the house between 1898 and 1909.

LANDSCAPE Northeast corner of Sleight and Benton; front and south sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: All alterations listed under "Post-2007" in "Alterations" field above.

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO 1892 Sanborn Map shows house without a front porch.
1898 Sanborn is first to show a full front porch on the house.

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; rear wood fence; similar setbacks; mature trees

COA DATE 6/27/2018

COA DECISION COA #18-2035 - Addition to the rear that wraps around to the front (approved by HPC 6/27/2018)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES: Addition appears to have not been constructed.



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

PREPARER Lara Ramsey

SURVEYDATE 12/4/2025

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR ROOF TYPE

DATESOURCE ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES Original 1890s house featured a front gable roof, rectangular massing, and full-width front porch. Early 1920s alterations/additions include the 2-story square projecting bay on the south elevation; one-story northwest corner addition; wraparound porch with solid knee walls and classical corner column and connecting sun porch with 4-light wood storm windows

ALTERATIONS 1/1 and 3/1 aluminum/vinyl replacement windows in original openings; 1 story rear addition; rear screen porch addition. Post-2007 -- no changes (exterior repainted)

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps show the house with a full front porch and one-story three-sided window bay on south elevation in 1921. A 2-story south addition, one-story northwest corner addition and new porch were constructed sometime between 1921 and 1926.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

SURVEYDATE

SURVEYAREA

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES L-shaped plan of original house; 1st story cutaway corners on south gable wing; carved wood bracket; historic 1/1 wood windows; front porch with hipped roof and solid knee walls is likely a historic replacement porch (c. 1915)

ALTERATIONS Front porch enclosed (post-1954); Aluminum siding (not historic); fixed shutters (not historic); 2nd-story rear addition (c. 1910-15); 1 story rear additions (south and north--post-1954). Post-2007 -- replacement storm door to enclosed front porch.

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southwest corner of Sleight and Franklin; front and south sidewalks; rear driveway; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	<input type="text" value="L-Form"/>	PLAN	<input type="text" value="T"/>
DETAILS	<input type="text" value="Italianate"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="c. 1875-80"/>	ROOF TYPE	<input type="text" value="Multi-gable"/>
OTHER YEAR	<input type="text" value="c. 1910"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor/Sanborn maps"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text" value="Leaded glass"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/single hung"/>
		WINDOW CONFIG	<input type="text" value="1/1"/>

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO House history questionnaire lists the date of construction as 1894. House is shown on 1892 Sanborn map with one-story porch extending across front façade of north wing only. Subsequent maps indicate that the current porch was built sometime between 1909 and 1921.

PERMITS

LANDSCAPE Northeast corner of Franklin and Sleight; front and south sidewalks; rear alley; similar setbacks; mature trees

COA DATE 9/2/2009; 8/24/2022

COA DECISION COA #09-2582 - Door Replacement (approved 9/2/2009); COA #22-3494 - Installation of aluminum clad wood windows to match style of home (approved 8/30/2022)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight
 \\images\25_Sleight
 \\images\25_Sleight
 \\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO 1892 Sanborn Map shows house with no front porch; 1898 map shows front entry porch, and 1909 map shows full front porch.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE 5/25/2017

COA DECISION COA 17-1607 - variance for detached garage (approved by HPC 5/25/2017)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

12/4/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION COA #24-2480 - one-story screened porch addition to the secondary façade that impacts the exterior architectural appearance of the primary façade of the principal structure, and a change in style for a new front door (approved by HPC 7/25/2024)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES: At time of field work, work on rear/south porch addition had not started. Replacement front door does not match door shown on drawings included with COA application -- my be an earlier replacement door that was installed between 2007 survey and COA app.

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; rear picket fence; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps indicate that the wraparound front porch was built sometime between 1909 and 1921.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear fencing; partial side driveway

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME Ellsworth School

COMMON NAME

COST 106350

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO The school was built to replace the previous school building (1879), which was declared unsafe by the State Fire Inspector in the 1920s. [From ELLSWORTH ELEMENTARY SCHOOL: SIXTY YEARS]

PERMITS According to info in NHS files, a four-room add. was built in the 1950s, and an administrative wing (\$226,000) added in 1982. [from ELLSWORTH ELEMENTARY SCHOOL: SIXTY YEARS]

LANDSCAPE Southwest corner of Sleight and School; front and north sidewalks; playground to south; parking lot on west side; chain link fence

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE 12/4/2025

SURVEYAREA NAPERVILLE HISTORIC DISTRICT



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: Replacement multi-light windows in arched openings at first story of north elevation.

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR ROOF TYPE

DATESOURCE ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps indicate that brick veneer was applied to the exterior of the house sometime between 1949 and 1954.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; side driveway; rear alley; rear fencing; similar setbacks; mature trees

COA DATE 6/23/2022

COA DECISION COA #22-2419 - In-kind roof replacement (approved 7/6/2022)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh
 \\images\25_Sleight
 \\images\25_Sleight
 \\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO 1898 Sanborn map shows full width front porch across front of original house; 1921 map shows north entry addition and wraparound front porch that has since been removed.

PERMITS

LANDSCAPE Southeast corner of School and Sleight; retaining wall at north side; front and north sidewalks; rear driveway; similar setbacks; mature trees

COA DATE 1/27/2011

COA DECISION COA 10-3451 - Install a French double door on the west elevation of the south wing of the home in place of an existing window (approved by HPC 1/27/2011)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES: South deck addition; replacement windows in original and altered openings; replacement railings at entry porch; replacement front door.



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

PREPARER Lara Ramsey

SURVEYDATE 12/4/2025

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleight
 \\images\25_Sleight
 \\images\25_Sleight
 \\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps indicate this was likely an Italianate house from the late 1870s or early 1880s -- the maps show a polygonal window bay on the front (west) elevation and front and side porches that are typical of homes of the style. Multiple alterations likely date from the post-WWII period -- aerial maps indicate these changes were made sometime between 1956 and 1978.

PERMITS

LANDSCAPE Northeast corner of Sleight and School; front and south sidewalks; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northwest corner of School and Sleight; front sidewalk; side driveway; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\imagest\25_Sleigh

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\sleight21

\\images\sleight213

\\images\sleight213

\\images\sleight213

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: replacement siding; 6/6 and 4/4 double-hung vinyl replacement windows throughout; replacement entry steps; shed-roof entry canopy replaced with gabled canopy; south entry porch enclosed

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION COA #23-3000 - In-kind window replacement maintaining grid pattern and use of aluminum clad wood (approved 9/5/2023)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southwest corner of North and Sleight; front and east sidewalks; principal façade on north; mature trees; similar setbacks

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: 1/1 double-hung Aluminum replacement windows throughout.

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS 1898-1943 Sanborn maps show house with south entry porch.

LANDSCAPE Southeast corner of North and Sleight; front and north sidewalks; rear driveway; similar setbacks; mature trees

COA DATE 7/2/2024; 2/14/2025; 12/28/2024

COA DECISION COA #24-2712 - In-kind window replacement wood, double-hung, grid configuration to match existing (approved 7/11/2024); COA 25-0025 - In-kind replacement of front door, and enclosed porch storm windows, storm door (approved 2/20/2025); COA #24-3622 - removal and replacement of windows on the primary façade of the enclosed front porch of the principal structure with use of fiberglass material (approved by HPC 1/23/2025)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS

SURVEYDATE 11/14/2007

SURVEYAREA NAPERVILLE



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW TYPE

WALL MATERIAL 2 (original) WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME Lueben, Fred A. House

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER West, John A.

ARCHITECT SOURCE

HISTORIC INFO House remained in the Lueben family until the death of Helen Leuben in 1999, when it was sold to the current owners.

PERMITS

LANDSCAPE Southwest corner of Sleight and Benton; front and north sidewalks; rear alley; similar setbacks; mature trees

COA DATE 10/4/2012

COA DECISION COA #12-3810 - Roof replacement (approved 10/8/2012)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

SURVEYDATE

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: Most 1/1 windows appear to be Aluminum/vinyl replacement windows. Railings added to front porch steps.

SURVEYDATE 12/4/2025

SURVEYAREA NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO The 1892 Sanborn Map shows the house with no front porch. Subsequent maps indicate that a new south side entry and wraparound porch were constructed sometime between 1898 and 1909—porch removed after 1954.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley/parking; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh
 \\images\25_Sleigh
 \\images\25_Sleigh
 \\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW TYPE

WALL MATERIAL 2 (original) WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO According to owner, Unger was local builder & resident of the house through the early 1900s. NHS walking tour brochure lists John A. West as first owner. The house originally featured a corner tower with mansard roof identical to that seen on 21 S. Sleight Street.

PERMITS House featured on p. 404 of A GUIDE TO CHICAGO'S HISTORIC SUBURBS.

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: 1/1 replacement windows on second story of front façade and upper floors of north bay.

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME Harter, John House

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

SURVEYDATE

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: Porch steps being replaced.

12/4/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleigh

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS According to owner, the house was originally built in 1908. Sanborn maps support this date (house first shows up on 1909 maps).

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; large south side yard; mature trees

COA DATE 1/30/2006

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

SURVEYDATE

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

SURVEYDATE 12/4/2025

SURVEYAREA NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME Moyer, David N. House

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO House featured on p. 404 of A GUIDE TO CHICAGO'S HISTORIC SUBURBS.

PERMITS

LANDSCAPE Northwest corner of Sleight and Van Buren; front and south sidewalks; rear alley; similar setbacks; mature trees

COA DATE 8/12/2013

COA DECISION COA #13-3010 - Removal of wood rear porch and construction of a rear porch to match the front porch (amendment to COA 12-0751, approved 8/14/2013); COA #12-0751 - addition (approved by HPC 4/26/2012)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

SURVEYDATE

PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: replacement windows under front and side gables appear to be in enlarged openings

12/4/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northeast corner of Sleight and Van Buren; front and south sidewalks; rear alley; similar setbacks; mature trees

COA DATE 1/24/2020

COA DECISION COA #19-3676 -- home remodeling including replacement wraparound front porch, 2/2 aluminum replacement windows, some in altered openings; new wood siding and trim; 2-story north/rear addition; new roof

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

SURVEYDATE

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

12/4/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southwest corner of Sleight and Van Buren; front and north sidewalks; rear alley; similar setbacks; mature trees

COA DATE 12/23/2018; 1/24/2019

COA DECISION COA #19-24 - In-kind window replacement. Picture window requires HPC approval for style change (approved 1/3/2019); COA #19-25 - Change in window style (Approved with conditions by HPC. Appealed conditions to CC 3/19/2019. Approved by CC without conditions).

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

12/4/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight
 \\images\25_Sleight
 \\images\25_Sleight
 \\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

SIGNIFICANT FEATURES

ALTERATIONS

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; rear picket fence; similar setbacks; mature trees

COA DATE

COA DECISION COA #17-480 - In-kind replacement of front door (approved 2/23/2017)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleigh

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW TYPE

WALL MATERIAL 2 (original) WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear picket fence

COA DATE 12/2/2013

COA DECISION COA #13-4152 - Front porch deck and ceiling addition, new columns, re-side dormer, re-roof (approved by HPC 11/14/2013)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

SURVEYDATE

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

SURVEYDATE 12/4/2025

SURVEYAREA NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; mature trees; rear alley

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear driveway; similar setbacks; mature trees

COA DATE 7/29/2009

COA DECISION COA #09-2168 - Roof replacement (approved)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE 12/4/2025

SURVEYAREA NAPERVILLE HISTORIC DISTRICT



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: Replacement front door.

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO House's original design almost identical to that at 120 S. Sleight--may have been the same builder.

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE 9/15/2017

COA DECISION COA #17-4022 - In-kind window replacement (approved 9/21/2017); COA #17-622 - Remove and replace front porch (approved by HPC 3/23/2017)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

SURVEYDATE 12/4/2025

SURVEYAREA NAPERVILLE HISTORIC DISTRICT

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS 1892-1954 Sanborn maps show house with front entry porch.

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear picket fence

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleigh

\\images\25_Sleight

\\images\25_Sleigh

\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATE

COA DECISION COA #15-2160 - In-kind replacement of roof shingles (approved 7/21/2015)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES: Asphalt shingle siding replaced with cedar shingle.

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: Replacement windows

\\images\25_Sleigh
\\images\25_Sleigh
\\images\25_Sleigh
\\images\25_Sleigh

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY	<input type="text" value="building"/>	HISTORIC FUNCTION	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="excellent"/>	REASON for SIGNIFICANCE	<input type="text" value="This distinctive Prairie School residence was designed by Harry Robinson, who worked as draftsman under Frank Lloyd Wright and Walter Burley Griffin."/>
INTEGRITY	<input type="text" value="not altered"/>		
SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Prairie School"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1914"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Plaque"/>	FOUNDATION	<input type="text" value="Concrete"/>
WALL MATERIAL (current)	<input type="text" value="Brick"/>	PORCH	<input type="text" value="Canopy"/>
WALL MATERIAL 2 (current)	<input type="text" value="Stucco"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text" value="Stucco"/>	WINDOW TYPE	<input type="text" value="casement"/>
		WINDOW CONFIG	<input type="text" value="Multi-light geometric"/>

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight

\\images\25_Sleight