

<b>STREET #</b>	132
<b>DIRECTION</b>	S
<b>STREET</b>	WRIGHT
<b>SUFFIX</b>	ST
<b>PIN</b>	0818323004
<b>LOCAL SIGNIFICANCE RATING</b>	S
<b>POTENTIAL IND NR? (Y or N)</b>	N
<b>Contributing to a NR DISTRICT?</b>	C
<b>Contributing secondary structure?</b>	C
<b>Listed on existing SURVEY?</b>	IHSS (O); Local District; NR

**GENERAL INFORMATION**

<b>CATEGORY</b>	building	<b>CURRENT FUNCTION</b>	Domestic - single dwelling
<b>CONDITION</b>	excellent	<b>HISTORIC FUNCTION</b>	Domestic - single dwelling
<b>INTEGRITY</b>	minor alterations	<b>REASON for SIGNIFICANCE</b>	Unusual, early example of Dutch Colonial Revival architecture, with broad side-gambrel roof and classical front porch.
<b>SECONDARY STRUCTURE</b>	Detached garage		

**ARCHITECTURAL DESCRIPTION**

<b>ARCHITECTURAL CLASSIFICATION</b>	Dutch Colonial Revival	<b>PLAN</b>	rectangular
<b>DETAILS</b>		<b>NO OF STORIES</b>	2
<b>BEGINYEAR</b>	c. 1905	<b>ROOF TYPE</b>	Side gambrel
<b>OTHER YEAR</b>		<b>ROOF MATERIAL</b>	Asphalt - shingle
<b>DATESOURCE</b>	NHS address file	<b>FOUNDATION</b>	Stone
<b>WALL MATERIAL (current)</b>	Wood	<b>PORCH</b>	Full front
<b>WALL MATERIAL 2 (current)</b>	aluminum	<b>WINDOW MATERIAL</b>	Wood
<b>WALL MATERIAL (original)</b>	Wood	<b>WINDOW MATERIAL</b>	Leaded glass
<b>WALL MATERIAL 2 (original)</b>		<b>WINDOW TYPE</b>	Double hung/single hung
		<b>WINDOW CONFIG</b>	3/1; 1/1
<b>SIGNIFICANT FEATURES</b>	Broad side gambrel roof with cornice returns; front gambrel centered along front façade; 3-sided south side window bay with leaded glass windows		
<b>ALTERATIONS</b>	Replacement 3/1 wood windows in original openings (historic--1920s); replacement front porch (historic); Aluminum awning on front 2nd story window (not historic)		

## HISTORIC INFORMATION

<b>HISTORIC NAME</b>	<input type="text"/>
<b>COMMON NAME</b>	<input type="text"/>
<b>COST</b>	<input type="text"/>
<b>ARCHITECT</b>	<input type="text"/>
<b>ARCHITECT2</b>	<input type="text"/>
<b>BUILDER</b>	<input type="text"/>
<b>ARCHITECT SOURCE</b>	<input type="text"/>

**HISTORIC INFO** Photograph of stenciling uncovered during rehab work says that house was built in 1905--no other information to substantiate that date.

**PERMITS**

**LANDSCAPE** Northeast corner of Wright and Chicago; oversized lot; front and south sidewalks; mature trees

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

\\Images\\wright132s.jpg

**DIGITAL PHOTO ID3**

\\Images\\wright132s(3).jpg

**DIGITAL PHOTO ID2**

\\Images\\wright132s(2).jpg

**DIGITAL PHOTO ID4**

\\Images\\wright132s(4).jpg