

STREET #	32
DIRECTION	S
STREET	SLEIGHT
SUFFIX	ST
PIN	0818317015
LOCAL SIGNIFICANCE RATING	PS
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - single dwelling
CONDITION	good	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	minor alterations and addition(s)	REASON for SIGNIFICANCE	Notable example of the type, with historic wraparound porch.
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gabled Ell	PLAN	irregular
DETAILS	Queen Anne	NO OF STORIES	2.5
BEGINYEAR	c. 1890	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Wood	PORCH	Wrap around
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Wood
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Stained glass
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Front gable bay with south side gable bay; 3-sided south window bay; historic 1/1 and 1-light wood windows		
ALTERATIONS	Rear porch addition; wrap around porch appears to be historic addition (hipped roof doesn't line up with front façade)		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Northeast corner of Sleight and Van
Buren; front and south sidewalks;
rear alley; similar setbacks; mature
trees

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

32

S

SLEIGHT



**DIGITAL
PHOTO ID**

\\images\sleight0
32s.jpg

**DIGITAL
PHOTO ID3**

\\images\sleight032s(
3).jpg

**DIGITAL
PHOTO ID2**

\\images\sleight0
32s(2).jpg

**DIGITAL
PHOTO ID4**

\\images\sleight032s(
4).jpg