

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Italianate"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text" value="Greek Revival"/>	NO OF STORIES	<input type="text" value="2"/>
BEGINYEAR	<input type="text" value="1874"/>	ROOF TYPE	<input type="text" value="Front gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="NHS Plaque"/>	FOUNDATION	<input type="text" value="Stone"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="full front/side"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Aluminum/vinyl"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text" value="glass block"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung"/>
		WINDOW CONFIG	<input type="text" value="2/2 vertical"/>

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	Barr, Samuel house
COMMON NAME	
ARCHITECT	
BUILDER	Barr, Samuel
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northwest corner of Franklin and Ellsworth; front and south sidewalks; side driveway; similar setbacks; mature trees
COA DATES	9/28/2012
COA DECISION	COA #12-3641 - replacement of [north] side entry porch (approved 10/2/2012)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	Replacement windows on north secondary elevation



**Work Completed Without COA** 2/2 double-hung replacement windows on front (east) façade and south elevation (facing Franklin Avenue) -- historically compatible type and configuration

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

# City of NAPERVILLE

## ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY CONTINUATION SHEET

STREET # 105

STREET N. ELLSWORTH STREET

---

### ADDITIONAL PHOTOS OR INFORMATION

#### *Historic Information*

1892 Sanborn Map shows no front porch; 1898 map shows front entry porch. Current porch has no entry/steps.

From A GUIDE TO CHICAGO'S HISTORIC SUBURBS, p. 401:

“This clapboard farmhouse, built in 1874, has the massing and details reminiscent of Greek Revival, but with pedimented window heads characteristic of the 1870s date. Added at the turn of the century was the porch with its four, standard, Tuscan columns. The west end of the building has a porch from the same construction campaign and columns selected from the same catalogue, but with slightly different proportions.”

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**  **SURVEYDATE**

**ORGANIZATION**  **SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Barr, Samuel House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	House history questionnaire submitted by owner includes chain of title/ownership information and tax records. Title research indicates that the property was owned by Samuel Barr at the time the house was constructed.
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/20/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	8/20/2018;4/26/2019
<b>COA DECISION</b>	COA #18-3335 - Replacing door with window and in-kind replacement matching existing window (approved 8/22/2018); COA #19-1196 - remove window replace with door - door existed prior to 2018 (approved 4/26/2019)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	Replacement windows in original and altered openings on north and south secondary elevations; two-story rear addition



**Work Completed Without COA**

Replacement windows on front façade;north end enclosure of front porch evident in 2007 survey removed; cast-stone steps to front porch flanked by brick planters; wrought iron railings added above north and south knee walls at front porch.

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/20/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	GUIDE TO CHICAGO'S HISTORIC SUBURBS ON WHEELS AND ON FOOT, P. 401 (Naperville #5).
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear picket fence
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

--

PREPARER	Lara Ramsey
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE	11/20/2025
SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Leffler, Jeremiah House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Naperville Historic District Website lists 129 N. Ellsworth as Jeremiah Leffler House, built in 1866. Building included in A GUIDE TO CHICAGO'S HISTORIC SUBURBS ON WHEELS AND ON FOOT, p. 401 (Naperville #6).
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

--

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/20/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

**SIGNIFICANT FEATURES** Front gable portion is original house (windows on first story appear historic); round arch window openings w/ center keystones; half round window under gable; round arch front entry; historic two-story south/rear addition constructed in 1903 (addition originally featured a second west-facing porch)

**ALTERATIONS** Paired brackets & dentils appear to be later (may be restoration); replacement windows on 2nd story or original structure (not historic); replacement door & transom (not historic); large 2 story S. side addition w/ corner tower (not historic--1990s); replacement porch (not historic-1990s); 1 story north bay addition (not historic); segmental arch window on 2nd story north elevation (not historic); chimney (not historic); rear screened porch addition (not historic). Post-2007 -- no changes.

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO According to history of the house in Naperville Heritage Society address file, the house was built in 1872. See IHSS photograph for original massing of house. According to A GUIDE TO CHICAGO'S HISTORIC SUBURBS (p. 401-2), the south/rear addition was constructed in 1903 and featured a west-facing porch. The porch was removed when the large 2-story addition with corner tower was constructed in the 1990s.

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; parking lot to south; similar setbacks; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fence
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	Replacement windows on north and south secondary elevations; aluminum siding around first story windows at west end of south elevation replaced.



<b>Work Completed Without COA</b>	6/1 vinyl replacement windows in existing openings on front façade; replacement front door;
-----------------------------------	---

<b>PREPARER</b>	Lara Ramsey
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS

<b>SURVEYDATE</b>	11/20/2025
<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Sporlein, Mary Elizabeth House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear alley; low stone wall around lot; similar setbacks; mature trees
<b>COA DATES</b>	6/27/2016
<b>COA DECISION</b>	COA #16-2362 - In-kind replacement of front porch (approved 7/11/2016)
<b>COA Compliance Notes</b>	Porch structure does not appear to have been replaced, but porch railing is replacement.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

Replacement windows on front façade.

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/20/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

**City of NAPERVILLE**  
2025 HISTORIC RESOURCES SURVEY UPDATE  
CONTINUATION SHEET

STREET # 135

STREET N. ELLSWORTH STREET

---

**ADDITIONAL PHOTOS OR INFORMATION**

*Alterations*

According to Sanborn Maps, house was originally a one-story structure that has been altered and added to over the years: 1 story south side addition is historic, but south porch appears to have been altered (replacement posts, railing, and steps, Aluminum under eaves); second story addition to original house is historic; first story on north addition was added sometime between 1926 and 1949, with 2<sup>nd</sup> story added after; aluminum siding; replacement windows in altered openings (not historic--house originally had a full porch and entry on front façade); multiple rear additions; stone steps to north side entry and stone patio at front of house (not historic)

*Post-2007 Alterations*

Windows on front façade appear to be newer 1/1 aluminum replacement windows; porch railing replaced.

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	Sanborn maps (1909-1949) show a larger inset corner entry porch that extends across east end of façade
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	7/10/2018
COA DECISION	COA #18-2732 - In-kind replacement of windows (approved 7/17/2018)
COA Compliance Notes	2007 survey photos show 1/1 double-hung windows on front and side elevations -- replacement windows are 2/2.
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	6/28/2012
<b>COA DECISION</b>	COA #12-2252 - Front steps replacement (approved 7/3/2012)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

Solar panels on roof--may have been present in 2007 and not noted on survey. 2007 survey photographs do not show slope of roof where panels are located.

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/20/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; similar setbacks; mature trees
<b>COA DATES</b>	12/7/2018
<b>COA DECISION</b>	COA #18-4656 - In-kind shingle replacement in areas where small fire occurred (approved 12/10/2018)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/20/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME** Schwartz, Charles House

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** See IHSS photograph for appearance of house before renovation. Featured on p. 402 of A GUIDE TO CHICAGO'S HISTORIC SUBURBS.

**PERMITS**

**LANDSCAPE** Southwest corner of Ellsworth and School; front and north sidewalks; rear alley; similar setbacks; mature trees

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/20/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE



**Work Completed Without COA**

**City of NAPERVILLE**  
2025 HISTORIC RESOURCES SURVEY UPDATE  
CONTINUATION SHEET

**STREET #** 151

**STREET** N. ELLSWORTH STREET

---

**ADDITIONAL PHOTOS OR INFORMATION**

*Alterations*

Recent renovation. Appropriate restoration work includes: replacement siding; replacement porch spindles and supports; replacement 1/1 windows; multi-light replacement windows on front bay; north entry porch; 1 story rear addition. Inappropriate alterations include glass block basement windows and a large 2-story addition to the south, including entry and porch, which is difficult to distinguish from the original massing of the home.

*Post-2007 Alterations*

No changes.

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Southeast corner of School and Ellsworth; front and north sidewalks; picket fence; rear driveway; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Helm, Daniel House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/20/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on west side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees

COA DATES 10/22/2020

COA DECISION COA #20-3281 - Made change without COA from brick to Bristol stone cast on the primary façade (denied by HPC on 10/22/20 and appeal denied by CC on 12/15/20)

COA Compliance Notes Cast stone remains in place.

COA Work Not Completed

Work Not Requiring COA Replacement windows on north and south secondary elevations; replacement door at ground-level south-side entry; entry porch and entrance toward rear of south elevation removed

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE



**Work Completed Without COA** Replacement windows on front façade, including in enclosed front porch

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE  WINDOW CONFIG

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Patterson, William Henry House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	McCorkel, Frank
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Patterson, a farmer in Wheatland Township, had the home built after his retirement.
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear driveway; similar setbacks; mature trees; rear wood fencing
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/20/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

Metal handrail added to steps on front porch -- this minor change may not require COA approval

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Tax records research by Naperville Heritage Society indicate that house was probably built around 1873.
<b>PERMITS</b>	Sanborn maps through 1949 show house with entry at front and no side porch.
<b>LANDSCAPE</b>	Southwest corner of Ellsworth and North; front and north sidewalks; south side yard; rear driveway; mature trees
<b>COA DATES</b>	11/14/2017
<b>COA DECISION</b>	COA #17-4764 - In-kind replacement of asphalt shingles (approved 11/14/2017)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	1/1 replacement windows in select openings on front façade and at west end of north elevation (facing North Avenue) at first story
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/20/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Southeast corner of North and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	11/23/2016
<b>COA DECISION</b>	COA #16-4595 - In-kind shingle replacement (approved 11/28/2016)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

Single window at north end of front façade under porch replaced with paired Aluminum 1/1 double-hung windows.

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	Historic photograph of building on p. 37 of NAPERVILLE HOMECOMING (1917). Sanborn maps from as early as 1898 list building being used as a sausage factory.
PERMITS	
LANDSCAPE	Southeast corner of Ellsworth and Benton; front and north sidewalks; building comes to sidewalk; street parking; attached to building at 8 S. Ellsworth on S side
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/20/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Owner indicated that the building was originally an ice house that was attached to 4-6 S. Ellsworth.

**PERMITS** Sanborn Maps indicate that original 2 story building was extended south and east between 1898 and 1909--front porch, windows, and entry probably date from that time.

**LANDSCAPE** Midblock on east side of residential street; attached to 4-6 S. Ellsworth on N. side; front sidewalk; rear alley; front planting

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Building does not appear on 1869 Bird's Eye View of Naperville, but is present on the 1886 Sanborn Map. Sanborn maps also indicate that the full-front porch was constructed sometime between 1909 and 1921.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA** Chimney on secondary south elevation demolished.

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA** Aluminum/vinyl replacement windows on 2nd story of front façade

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATE SOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Sanborn maps indicate that the building was converted into a duplex sometime between 1921 and 1926.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; large south side yard; mature trees

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION

INTEGRITY

REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Side yard associated with 16 S. Ellsworth Street.

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

**Work Completed Without COA**

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR  ROOF TYPE

DATESOURCE  ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Metz, Adam House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Chain of title indicates Metz purchased property from Alvin Scott in 1874 for \$440. Inventory of Metz estate date 1878 makes mention of house.
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; rear and side picket fence; large south side yard; mature trees
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/20/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Neo-Traditional"/>	PLAN	<input type="text" value="L"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="2012"/>	ROOF TYPE	<input type="text" value="Multi-gable"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Standing seam metal"/>
DATESOURCE	<input type="text" value="COA"/>	FOUNDATION	<input type="text" value="Concrete"/>
WALL MATERIAL (current)	<input type="text" value="Fiber Cement Board"/>	PORCH	<input type="text" value="Wrap around"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Aluminum/vinyl"/>
WALL MATERIAL (original)	<input type="text" value="-"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="Casement/fixed"/>
		WINDOW CONFIG	<input type="text" value="2-light; 4-light"/>

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Former site of late 19th century Greek Revival residence rated "C" in 2007 survey. Historic maps indicate that the building was likely constructed early 1870s.

**PERMITS**

**LANDSCAPE** Northeast corner of S. Ellsworth and Van Buren; front and south sidewalks; rear/south picket fence; rear alley; oversize lot; mature trees

**COA DATES** 5/6/2016; 1/26/2012

**COA DECISION** COA #15-3111 - Addition of 2 upper story windows, modifying screen porch to windows (approved 3/28/2016); COA #11-2993 - demolition of the existing structure and new construction (approved by HPC 1/26/2012); COA #13-3320 - Modifications to the site plan and Building Elevations approved through COA #11-2293 (approved by HPC 9/26/2013); COA #15-3111 - construction of new residence (tabled by HPC 9/24/2015, approved 10/29/2015)

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southeast corner of Van Buren and Ellsworth; front and north sidewalks; rear alley; similar setbacks; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Sanborn maps indicate that the house was constructed sometime between 1949 and 1954.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; similar setbacks; mature trees

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA**

1/1 replacement windows on attic level and in front dormer.

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Aerial photographs indicate that the center entry porch was constructed sometime between 1978 and 1987.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; partial side driveway; rear alley; similar setbacks; mature trees

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Sanborn maps indicate the house originally featured a two-story north wing with a one-story west-facing porch, which was removed sometime between 1921 and 1926.

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees

**COA DATES** 5/18/2018

**COA DECISION** COA #18-1902 - In-kind replacement of windows (approved 5/23/2018)

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

**SIGNIFICANT FEATURES**

**ALTERATIONS**

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Stenger, Elizabeth House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	History provided by owner during 2007 survey.
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	4/19/2020
<b>COA DECISION</b>	COA #20-831 - In-kind shingle replacement (approved 4/23/2020)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	
<b>PREPARER</b>	Lara Ramsey
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS
<b>SURVEYDATE</b>	11/20/2025
<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE



<b>Work Completed Without COA</b>	
-----------------------------------	--

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Minimal Traditional"/>	PLAN	<input type="text" value="L"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1"/>
BEGINYEAR	<input type="text" value="1953-54"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Owner"/>	FOUNDATION	<input type="text" value="Not visible"/>
WALL MATERIAL (current)	<input type="text" value="Stone veneer"/>	PORCH	<input type="text" value="Front entry"/>
WALL MATERIAL 2 (current)	<input type="text" value="Brick"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Stone veneer"/>	WINDOW MATERIAL	<input type="text" value="Glass block"/>
WALL MATERIAL 2 (original)	<input type="text" value="Brick"/>	WINDOW TYPE	<input type="text" value="double hung/fixed"/>
SIGNIFICANT FEATURES	<input type="text" value="Stone veneer on façade; hipped roof with overhanging eaves; rounded corner entry; historic double hung &amp; multi-light wood windows; 3-sided front window bay; glass block beside entry"/>		
ALTERATIONS	<input type="text" value="Post-2007 -- no changes."/>		

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Feldott, Ralph House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	lot was originally part of 126 S. Ellsworth, according to owner (2007 survey)
<b>PERMITS</b>	
<b>LANDSCAPE</b>	midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/20/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE