

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Geiger, C. H. House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Geiger was president of North Central College from 1946-1960. House was featured in Naperville Heritage Housewalk Brochure.
<b>PERMITS</b>	Certificate of Rehabilitation issued January 2007.
<b>LANDSCAPE</b>	Northwest corner of Columbia and Benton; front and south sidewalks; side driveway; similar setbacks; mature trees; rear wood fence
<b>COA DATES</b>	1/4/2017; 5/19/2017
<b>COA DECISION</b>	COA #17-36 - In-kind window and siding replacement (approved 1/5/2017); COA #17-1941 - in-kind replacement of asphalt shingles (approved 5/23/2017)
<b>COA Compliance Notes</b>	COA-approved work does not appear to have been completed.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/13/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Northeast corner of Columbia and Benton; front and south sidewalks; side driveway; similar setbacks; mature trees; front plantings
<b>COA DATES</b>	9/8/2009; 11/17/2016; 1/28/2021; 3/24/2022
<b>COA DECISION</b>	COA # 09-2172 - Replacement of front porch concrete steps (approved 9/8/2009); COA #16-4092 - recess entry door, rebuild and change dormer, create new entry and window openings, change several existing windows (approved by HPC 11/17/2016); COA #20-4723 - Carport attached to the primary structure (approved COA and recommended approval of variance 1/28/2021. Variance approved by CC 3/2/2021); COA #22-252 - New rear deck on corner lot, new ornamental fence on porte cochere, skylight (approved by HPC 3/24/22 with the condition that the pillars of the new deck be constructed of masonry to match existing elements of the residence)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	Work approved in COA #22-252 appears to have not been undertaken. Window replacement in south dormer (approved, COA #16-4092) also not undertaken.
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/19/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Houghton, Walter E. House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	Folding doors replaced with overhead door on detached garage.



**Work Completed Without COA**

--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/13/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear picket fence
COA DATES	3/21/2019
COA DECISION	COA #19-487 - alteration in front porch style (approved by HPC 3/21/2019)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	Siding painted.



<b>Work Completed Without COA</b>	Replacement windows on front façade

PREPARER	Lara Ramsey
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE	11/13/2025
SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; partial driveway; rear alley; similar setbacks; mature trees
COA DATES	8/13/2015
COA DECISION	COA #15-2811 - In-kind replacement of roof shingles (approved 8/14/2015)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

Removal of non-historic awnings from front façade--may not require COA.

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Umbreit, Franklin House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	7/30/2021; 4/6/2022
<b>COA DECISION</b>	COA #21-2777 - In-kind porch pillar and stairs replacement (approved 8/4/2021); COA #22-1096 - In-kind window replacement (approved 4/19/2022)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

--

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/19/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Goehring, Louis and Verena House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Southwest corner of Franklin and Columbia; front and north sidewalks; rear driveway; similar setbacks; mature trees; rear & south picket fence
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	Square oriel bay addition on first story of secondary south elevation.



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/5/2007
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Residents (2007 survey )reported that two-toned brick was original feature of home; Sanborns also show brick veneer on exterior, with no indications of stucco/wood at 2nd story.

**PERMITS**

**LANDSCAPE** Southeast corner of Franklin and Columbia; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fencing

**COA DATES** 9/24/2020

**COA DECISION** COA #20-3635 - In-kind front porch stair replacement (approved 9/28/2020)

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/19/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE



**Work Completed Without COA**

STREET # 106  
 DIRECTION N  
 STREET COLUMBIA  
 SUFFIX ST  
 PIN 0818400011  
 LOCAL SIGNIFICANCE RATING S  
 POTENTIAL IND NR? (Y or N) N  
 Contributing to a NR DISTRICT? C  
 Contributing secondary structure? NC  
 Listed on existing SURVEY? Local District; NR District



**GENERAL INFORMATION**

CATEGORY building HISTORIC FUNCTION Domestic - single dwelling  
 CONDITION excellent REASON for SIGNIFICANCE One of several intact, early 20th-century examples of the style along Columbia Avenue, with an appropriately-placed rear addition.  
 INTEGRITY minor alterations and addition(s)  
 SECONDARY STRUCTURE Detached garage

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION American Foursquare PLAN rectangular  
 DETAILS Queen Anne - Free Classic NO OF STORIES 2.5  
 BEGINYEAR c. 1905 ROOF TYPE Hipped  
 OTHER YEAR ROOF MATERIAL Asphalt - shingle  
 DATESOURCE Surveyor FOUNDATION Concrete - block  
 WALL MATERIAL (current) Wood PORCH Full front  
 WALL MATERIAL 2 (current) Wood - shingle WINDOW MATERIAL wood  
 WALL MATERIAL (original) Wood WINDOW MATERIAL beveled glass  
 WALL MATERIAL 2 (original) Wood - shingle WINDOW TYPE double hung/casement/fixe  
 WINDOW CONFIG 1/1; multi-light

**SIGNIFICANT FEATURES** Flared hipped roof with overhanging eaves; front & side hipped dormers; full front porch with hipped roof, rounded columns & square railings; wood shingle 2nd story (slight flare at 2nd story break); historic wood windows; 3-sided, 2-story south bay

**ALTERATIONS** Replacement front steps (not historic); large 2 story rear addition, with 2nd south bay and rear porch (not historic). Post-2007 -- no changes.

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	1926 Sanborn Map shows building without rear addition.
<b>LANDSCAPE</b>	Northeast corner of Columbia and Franklin; front and south sidewalks; rear alley; rear wood fence; similar setbacks; mature trees
<b>COA DATES</b>	12/29/2024
<b>COA DECISION</b>	COA #24-3631 - a solid fence abutting a corner side yard on the property and is visible from a public street (approved by HPC 1/23/2025)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**Work Completed Without COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees; rear wood fence

COA DATES 5/24/2018

COA DECISION COA #18-1491 - addition to rear that wraps around the front (withdrawn)

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA Aluminum double-hung replacement windows on first story on secondary north and south side elevations.

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	6/24/2011;
<b>COA DECISION</b>	COA #11-2071 - Window replacement (approved 6/28/2011); COA #13-1360 - keep the south dormer (constructed without a COA) with modifications (approved by HPC 7/25/2013)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	Heritage Place Building #9
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	This grouping of row houses is part of a larger residential development surrounding the P. E. Kroehler House.
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; mature trees in parkway; similar front setbacks; rear driveway
<b>COA DATES</b>	11/19/2019; 10/20/2020
<b>COA DECISION</b>	COA #19-2840 -- approval of demolition of properties on block (approved by City Council 11/19/2019); COA #20-2321 -- construction of town home units and rehab of Kroehler Mansion (denied by HPC, approved by City Council 10/20/2020 subject to administrative approval of revised plans for Heritage Place).
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/13/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Vocks, Herman House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; mature trees; similar setbacks
<b>COA DATES</b>	7/17/2015
<b>COA DECISION</b>	COA #15-2384 - In-kind replacement of front porch (approved 7/21/2015). City records state that the application was closed due to inactivity -- work may have been undertaken after COA expired.
<b>COA Compliance Notes</b>	Fascia board on replacement porch features square blocks above columns that were not present on previous porch -- design of porch as built falls within the "acceptable" guidelines for replacement porches outlined in the Historic Building Design and Resource Manual.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE


WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley and side driveway; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
----------------------------	--

PREPARER	Lara Ramsey
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE	11/19/2025
SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION

INTEGRITY

REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION

DETAILS

BEGINYEAR

OTHER YEAR

DATESOURCE

WALL MATERIAL (current)

WALL MATERIAL 2 (current)

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

PLAN

NO OF STORIES

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Open park district area planned as part of a larger residential development surrounding the P. E. Kroehler House.

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**Work Completed Without COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET # 135-139  
 DIRECTION N  
 STREET COLUMBIA  
 SUFFIX ST  
 PIN  
 LOCAL SIGNIFICANCE RATING NC  
 POTENTIAL IND NR? (Y or N) N  
 Contributing to a NR DISTRICT? NC  
 Contributing secondary structure? -  
 Listed on existing SURVEY? -



**GENERAL INFORMATION**

CATEGORY building HISTORIC FUNCTION  
 CONDITION REASON for SIGNIFICANCE  
 INTEGRITY  
 SECONDARY STRUCTURE -

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION Row Houses - Neo-Traditional (under construction) PLAN  
 DETAILS NO OF STORIES  
 BEGINYEAR 2026 ROOF TYPE  
 OTHER YEAR ROOF MATERIAL  
 DATESOURCE Surveyor FOUNDATION  
 PORCH  
 WALL MATERIAL (current) WINDOW MATERIAL  
 WALL MATERIAL 2 (current) WINDOW MATERIAL  
 WALL MATERIAL (original) WINDOW TYPE  
 WALL MATERIAL 2 (original) WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**Work Completed Without COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

--

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	6/23/2016; 8/25/2016
COA DECISION	COA #16-2362 - Replacement of aluminum siding with fiber cement siding & replacement of windows with aluminum clad windows (approved 6/24/2016); COA #16-2823 - change in porch style (tabled by HPC 8/4/2016, approved 8/25/2016)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

--

PREPARER	Lara Ramsey
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE	11/19/2025
SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET # 143-147  
 DIRECTION N  
 STREET COLUMBIA  
 SUFFIX ST  
 PIN  
 LOCAL SIGNIFICANCE RATING NC  
 POTENTIAL IND NR? (Y or N) N  
 Contributing to a NR DISTRICT? NC  
 Contributing secondary structure? -  
 Listed on existing SURVEY? -



**GENERAL INFORMATION**

CATEGORY building HISTORIC FUNCTION N/A  
 CONDITION REASON for SIGNIFICANCE  
 INTEGRITY  
 SECONDARY STRUCTURE -

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION Row Houses - Neo-Traditional (under construction) PLAN  
 DETAILS NO OF STORIES  
 BEGINYEAR 2026 ROOF TYPE  
 OTHER YEAR ROOF MATERIAL  
 DATESOURCE Surveyor FOUNDATION  
 PORCH  
 WALL MATERIAL (current) WINDOW MATERIAL  
 WALL MATERIAL 2 (current) WINDOW MATERIAL  
 WALL MATERIAL (original) WINDOW TYPE  
 WALL MATERIAL 2 (original) WINDOW CONFIG  
 SIGNIFICANT FEATURES  
 ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**Work Completed Without COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

**SIGNIFICANT FEATURES** Pent front gable w/ overhanging eaves; rounded 1st & 2nd story front window bays; full front porch w/ shed roof, stucco knee walls, & square wood columns; leaded glass windows north of front door; S. square window bay; leaded glass windows on north and south ends of dining room (rear elevation), and center leaded glass window between 3/1 wood windows on east side of dining room

**ALTERATIONS** 3/1 replacement windows under front gable, rear gable, and north dormer (not historic); wrought iron railings at front steps; dormer addition on east (rear) elevation. Post-2007 -- 1/1 and 3/1 Aluminum replacement windows in original openings.

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Spreng, Bishop Samuel House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Subsequent owners of the house included Ben and Lucille Baumgartner Groves (1947-c. 1965); Burton and Patricia Ericson (1965-1985). Owners stated in house history questionnaire that they had been told the two homes directly north were built for family members of the owners of 146 N. Columbia Street. House featured in the February 4, 1960 edition of the Naperville Sun (page 1, section two).
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; rear fencing; similar setbacks; mature trees
<b>COA DATES</b>	8/16/2012; 4/6/2022
<b>COA DECISION</b>	COA #12-2903 - Repair damaged roof, soffit and fascia (approved 8/20/2012); COA #22-1099 - In-kind window replacement (approved 4/19/2022)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	1/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; rear wood fencing; similar setbacks; mature trees
<b>COA DATES</b>	12/12/2011
<b>COA DECISION</b>	COA #11-4105 - Add railing for front porch stairs (approved 12/15/2011)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	Work approved by COA not undertaken.
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Southeast corner of Columbia and School; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees
<b>COA DATES</b>	11/17/2017
<b>COA DECISION</b>	COA #17-4813 - In-kind replacement of asphalt shingles (approved 10/12/2017)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	Replacement door in south side secondary entrance opening.



**Work Completed Without COA**

Replacement door to enclosed front porch (may be considered a storm door, which would not require COA)

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northwest corner of Columbia and School; front and south sidewalks; rear driveway; rear fencing; similar setbacks; mature trees
COA DATES	5/26/2011
COA DECISION	COA #11-1157 - demolition of an existing staircase, awning and bracket to accommodate a new building addition, including enclosed porch on the rear (west) side of the home (approved by HPC 5/26/2011)
COA Compliance Notes	
COA Work Not Completed	Work approved by COA appears to have not been undertaken.
Work Not Requiring COA	



**Work Completed Without COA**

PREPARER	Lara Ramsey	SURVEYDATE	11/13/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="American Foursquare"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text" value="Prairie"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="1907"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Owner"/>	FOUNDATION	<input type="text" value="Parged"/>
WALL MATERIAL (current)	<input type="text" value="Stucco"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood"/>
WALL MATERIAL (original)	<input type="text" value="Stucco (over clay brick)"/>	WINDOW MATERIAL	<input type="text"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/casement"/>
SIGNIFICANT FEATURES	<input type="text" value="Broad hipped roof with overhanging eaves; front hipped dormer; full width front porch with hipped roof, square stucco columns on solid knee walls, and curved frieze; historic 3/1 and 2-light wood windows"/>		
ALTERATIONS	<input type="text" value="1 story rear addition. Post-2007 -- no changes."/>		

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="American Foursquare"/>	PLAN	<input type="text" value="Rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="2.5"/>
BEGINYEAR	<input type="text" value="c. 1905"/>	ROOF TYPE	<input type="text" value="Hipped"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="surveyor"/>	FOUNDATION	<input type="text" value="Concrete - block"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Full front"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="Wood/Aluminum"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text" value="Leaded glass"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="Double &amp; single hung/casemen"/>
		WINDOW CONFIG	<input type="text" value="3/1; multi/1; 3 &amp; 1-light"/>

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

3/1 replacement windows in original openings on front façade (historically compatible type and configuration); wrought iron railings at front steps replaced with painted wood railings

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

--

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; side driveway; similar setbacks; mature trees
<b>COA DATES</b>	8/26/2010; 1/25/2018
<b>COA DECISION</b>	COA#10-2177 - Replacement of siding with vinyl (denied by HPC 8/26/2010); COA #18-56 - Add two dormers, add shutters and brackets, repair the foundation base and vertical lattice, replace the stairs and railing system, replace three windows, put in wood siding and asphalt shingles, alter the front door (approved by HPC 1/25/2018)
<b>COA Compliance Notes</b>	Design of north and south dormers not consistent with design shown in exhibit included with COA approval.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	Rear porch addition (pre-2018); replacement windows in altered openings on north and south secondary elevations (pre-2018)



**Work Completed Without COA**

--

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/19/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE

STREET # 219  
 DIRECTION N  
 STREET COLUMBIA  
 SUFFIX ST  
 PIN 0818205002  
 LOCAL SIGNIFICANCE RATING C  
 POTENTIAL IND NR? (Y or N) N  
 Contributing to a NR DISTRICT? C  
 Contributing secondary structure? C  
 Listed on existing SURVEY? Local District; NR District



**GENERAL INFORMATION**

CATEGORY building HISTORIC FUNCTION Domestic - single dwelling  
 CONDITION good REASON for SIGNIFICANCE  
 INTEGRITY minor alterations and addition(s)  
 SECONDARY STRUCTURE Detached garage

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION Craftsman PLAN rectangular  
 DETAILS NO OF STORIES 2.5  
 BEGINYEAR c. 1920 ROOF TYPE Side gable  
 OTHER YEAR ROOF MATERIAL Asphalt - shingle  
 DATESOURCE Surveyor FOUNDATION Parged  
 PORCH Full front  
 WALL MATERIAL (current) Fiber Cement Board WINDOW MATERIAL aluminum  
 WALL MATERIAL 2 (current) Fiber Cement Shingles WINDOW MATERIAL Wood  
 WALL MATERIAL (original) Wood WINDOW TYPE Double hung/casement/awning  
 WALL MATERIAL 2 (original) WINDOW CONFIG 3/1; 3-light; 1-light

**SIGNIFICANT FEATURES** Side gable roof; full-width front porch with low-pitched gable roof, square corner piers, and solid knee walls

**ALTERATIONS** Front dormer enlarged with replacement windows; window bay addition (south); green house window (south); fixed shutters; greenhouse window on south elevation; turned wood columns on porch; two story rear addition. Post-2007 -- stucco cladding replaced with fiber cement board and shingle siding; square corner porch piers and center turned columns replaced with square wood piers; replacement wood railing at porch steps; 3/1 Aluminum replacement windows on front façade; one-story rear sunporch addition

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; rear alley; front sidewalk; rear picket fence; similar setbacks; mature trees
COA DATES	7/13/2023
COA DECISION	COA #23-1731 - Change in material for front porch walls and roof, change in style for front porch columns and the introduction of railings on the front porch stairs (approved by HPC 7/13/2023)
COA Compliance Notes	COA application (COA #23-1731) shows the existing stucco cladding remaining outside of the porch walls, section of front façade under porch, and front dormer.
COA Work Not Completed	
Work Not Requiring COA	



<p><b>Work Completed Without COA</b></p>	<p>Replacement windows on 2nd story of front façade (historically compatible type and configuration)</p>
--	--

PREPARER	Lara Ramsey	SURVEYDATE	11/19/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	<input type="text" value="Queen Anne - Free Classic"/>	PLAN	<input type="text" value="rectangular"/>
DETAILS	<input type="text"/>	NO OF STORIES	<input type="text" value="1.5"/>
BEGINYEAR	<input type="text" value="c. 1910"/>	ROOF TYPE	<input type="text" value="Combination"/>
OTHER YEAR	<input type="text"/>	ROOF MATERIAL	<input type="text" value="Asphalt - shingle"/>
DATESOURCE	<input type="text" value="Surveyor"/>	FOUNDATION	<input type="text" value="Concrete - block"/>
WALL MATERIAL (current)	<input type="text" value="Wood"/>	PORCH	<input type="text" value="Front (enclosed)"/>
WALL MATERIAL 2 (current)	<input type="text"/>	WINDOW MATERIAL	<input type="text" value="wood"/>
WALL MATERIAL (original)	<input type="text" value="Wood"/>	WINDOW MATERIAL	<input type="text" value="Vinyl/leaded glass"/>
WALL MATERIAL 2 (original)	<input type="text"/>	WINDOW TYPE	<input type="text" value="double hung/fixed"/>
		WINDOW CONFIG	<input type="text" value="1/1; diamond"/>

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE** Southeast corner of Columbia and North; front and north sidewalks; rear driveway; similar setbacks; mature trees

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**  **SURVEYDATE**

**ORGANIZATION**  **SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Attig, Jacob House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	Fry, Oliver
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Southwest corner of Columbia and North; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees
<b>COA DATES</b>	4/2/2012
<b>COA DECISION</b>	COA # 12-0862 - Roof replacement (approved 4/6/2012)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/13/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Southwest corner of Columbia and Benton; front and north sidewalks; side driveway; similar setbacks; mature trees; rear picket fence
<b>COA DATES</b>	1/4/2017; 5/3/2019
<b>COA DECISION</b>	COA #17-36 - in-kind window and siding replacement (approved 1/5/2017); COA #19-1373 - In-kind replacement of porch columns (approved 5/6/2019)
<b>COA Compliance Notes</b>	Wood shingles replaced with fiber cement board siding.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	Replacement front door.
-----------------------------------	-------------------------

**PREPARER** Lara Ramsey

**SURVEYDATE** 11/13/2025

**ORGANIZATION** RAMSEY HISTORIC CONSULTANTS

**SURVEYAREA** NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Sleight, William P. & Ida House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Southeast corner of Benton and Columbia; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees
<b>COA DATES</b>	12/12/2011; 9/8/2022; 7/2/2025; 10/16/2023
<b>COA DECISION</b>	See continuation sheet.
<b>COA Compliance Notes</b>	Escape window (#11-4104) not visible from public way.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

--

<b>PREPARER</b>	Lara Ramsey
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS

<b>SURVEYDATE</b>	11/19/2025
<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

**City of NAPERVILLE**  
ILLINOIS URBAN ARCHITECTURAL AND HISTORICAL SURVEY  
CONTINUATION SHEET

STREET # 8

STREET S. COLUMBIA STREET

---

**ADDITIONAL PHOTOS OR INFORMATION**

*COA Decisions*

- COA #11-4104 - Replace escape window (approved 12/15/2011)
- COA #22-3731 - Removal of existing 4.5" reveal horizontal lap wood siding and 3.5" wood window trim. Installation of James Hardie Fiber Cement 5" reveal horizontal lap siding (approved 9/15/2022)
- HPC-0000-2025 - In-kind roof replacement with asphalt shingles (approved 7/8/2025)
- COA #23-3861 - two-story addition to a secondary façade that impacts the exterior architectural appearance of the primary façade of the principal structure and alters the roof shape and height (approved by HPC 10/26/2023)

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Sohl, Lawrence House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	Chain of title for property from Naperville Heritage Society Address Files indicates house was built between 1905 & 1916.
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	Two-story rear addition that extends past south secondary elevation



**Work Completed Without COA**

--

<b>PREPARER</b>	Lara Ramsey
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS

<b>SURVEYDATE</b>	11/13/2025
<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	Schuler, Charles Royal House
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	Kiest, Charles
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	According to history of house located in address files at Naperville Heritage Society, Charles Schuler and his wife were Chicago natives. Charles worked as an electrical engineer for Commonwealth Edison.
<b>PERMITS</b>	Historic photos of house show that it was originally clad in stucco, with blind round arches above 1st story façade windows and round arch recessed front entry.
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; rear wood picket fence; similar setbacks; mature trees
<b>COA DATES</b>	
<b>COA DECISION</b>	
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

DATE SOURCE  PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**  **SURVEYDATE**

**ORGANIZATION**  **SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Owner during 2007 survey may have had original plans--architect was supposedly a student of Frank Lloyd Wright; same house built on N. Julian

**PERMITS**

**LANDSCAPE** Midblock on east side of residential street; front sidewalk; rear alley; rear picket fence; similar setbacks; mature trees

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
<b>COA DATES</b>	1/27/2010
<b>COA DECISION</b>	COA #10-0148 - Window Replacement (approved 1/27/2010)
<b>COA Compliance Notes</b>	Two new windows placed on either side of existing window under porch on front façade.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

Replacement front door; replacement railings at porch steps.

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/13/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	1926 and 1943 Sanborn Maps (sheets 7 and 12) show full width front porch on house.
<b>LANDSCAPE</b>	Midblock on east side of residential street; front sidewalk; rear alley; rear chain link fence; similar setbacks; mature trees
<b>COA DATES</b>	5/27/2021
<b>COA DECISION</b>	COA 21-1720 - Addition and new front porch. Variance to the front setback for porch (HPC approved COA and recommended approval of variance 5/27/21. Variance approved by CC 6/15/21)
<b>COA Compliance Notes</b>	Work appears to be consistent with elevation drawings and site plan included in COA application.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



<b>Work Completed Without COA</b>	
-----------------------------------	--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATION

PORCH

WALL MATERIAL (current)  WINDOW MATERIAL

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW TYPE

WALL MATERIAL 2 (original)  WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on west side of residential street; front sidewalk; rear alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

3/1 Aluminum replacement windows on front elevation (do not match original 4/1 configuration, but are historically compatible)

PREPARER	Lara Ramsey	SURVEYDATE	11/13/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Northwest corner of Columbia and Van Buren; front and south sidewalks; rear driveway; similar setbacks; mature trees

COA DATES 9/2/2009

COA DECISION COA #09-2589 - Roof replacement (approved 9/2/2009)

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER Lara Ramsey

SURVEYDATE 11/13/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	Map of Sears-Roebuck Kit home locations in NHS file (called "Sears Homes") indicates that this is a kit home.
PERMITS	
LANDSCAPE	Northeast corner of Columbia and Van Buren; front and south sidewalks; rear alley; large north side yard; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

Wood railing replaced with historically compatible new wood railing at front porch.

PREPARER Lara Ramsey

SURVEYDATE 11/19/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** During 2007 survey, Commission member stated that brick veneer was recently added (c. 1990-1995) and that building was original wood sided. Sanborn maps confirm that the building was originally wood frame.

**PERMITS**

**LANDSCAPE** Southwest corner of Columbia and Van Buren; front and north sidewalks; rear driveway; similar setbacks; mature trees

**COA DATES** 6/16/2022

**COA DECISION** COA #22-2105 - In-kind roof replacement (approved 6/23/2022)

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**

**PREPARER**

**SURVEYDATE**

**ORGANIZATION**

**SURVEYAREA**



**Work Completed Without COA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Southeast corner of Columbia and Van Buren; front sidewalk; rear driveway; similar setbacks; mature trees
<b>COA DATES</b>	10/7/2009
<b>COA DECISION</b>	COA #09-3056 - Steps Repair (approved 10/7/2009)
<b>COA Compliance Notes</b>	
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

Aluminum replacement windows at east and west ends of north elevation (facing Van Buren Avenue)

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/19/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street; large north side yard; front sidewalk; rear alley; mature trees
COA DATES	8/26/2013
COA DECISION	COA #13-2992 - Demolition of an existing front porch and construction of a new wrap around porch on the west and south facades of the home (approved 8/26/2013)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



**Work Completed Without COA**

PREPARER	Lara Ramsey
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS

SURVEYDATE	11/19/2025
SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO  
 Owner (2007) claimed that home underwent dramatic changes in the late 1930s. Sanborn maps from 1926 & 1943 show same massing, w/ 2 & 1-story wings. Porch is not shown on either map.

PERMITS

LANDSCAPE  
 Midblock on west side of residential street; large north side yard; front sidewalk; side driveway; mature trees

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA  
 Detached garage replaced

PREPARER

SURVEYDATE

ORGANIZATION

SURVEYAREA



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS

BEGINYEAR  NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**ARCHITECT**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATES**

**COA DECISION**

**COA Compliance Notes**

**COA Work Not Completed**

**Work Not Requiring COA**



**Work Completed Without COA**

**PREPARER**  **SURVEYDATE**

**ORGANIZATION**  **SURVEYAREA**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  HISTORIC FUNCTION

CONDITION  REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

<b>HISTORIC NAME</b>	
<b>COMMON NAME</b>	
<b>ARCHITECT</b>	
<b>BUILDER</b>	
<b>ARCHITECT SOURCE</b>	
<b>HISTORIC INFO</b>	
<b>PERMITS</b>	
<b>LANDSCAPE</b>	Northwest corner of Columbia and Chicago; front and south sidewalks; rear driveway; privacy plantings; mature trees
<b>COA DATES</b>	5/28/2020
<b>COA DECISION</b>	COA #20-610 - addition, front and rear porch, cantilevered box bay window (approved by HPC 5/28/2020)
<b>COA Compliance Notes</b>	Work approved by COA does not appear to have been completed.
<b>COA Work Not Completed</b>	
<b>Work Not Requiring COA</b>	



**Work Completed Without COA**

--

<b>PREPARER</b>	Lara Ramsey	<b>SURVEYDATE</b>	11/13/2025
<b>ORGANIZATION</b>	RAMSEY HISTORIC CONSULTANTS	<b>SURVEYAREA</b>	NAPERVILLE SURVEY UPDATE