Statics Progress Statics by Month

Painting Progress Paintings by Month

[6/19/2025, 12:00

AMI 118 BENTON,

[3/12/2025, 12:00

PM] 1209 JANE AV,

CCTV 2025 Warrenville Defects Identified Q Pipe Material 8 1,252 Other 2.44% Defects Summary Legend Lisle Vitrified Clay Pipe 25.46% CIPP 24.98% Broken: 45 Collapse: 1 Cracks/Fractures: 56 Ductile Iron Pipe 3.49% Deposits: 226 Holes: 1 Infiltrations: 149 Polyvinyl Chloride 41.1% Intruding Sealing Rings: 177 Intruding Taps: 0 Joints Offset/Separated: 12 Naperville Liner Defects: 80 < Obstructions: 0 Root Balls: 2 **CCTV Progress** Roots: 472 32.1 mi televised 22.58 mi 9.52 mi City Contractor

City of Naperville, County of DuPage, Esri, TomTom, Garmin, SafeGraph, GeoTechnologies, Inc, METI/NASA, USGS, EPA, NPS, USDA, USFWS

Annual Goal: 62.39% complete


City of Naperville Lead Service Line Replacement

The City of Naperville's Lead Service Line

Replacement Program is working towards removing all known lead service lines within the city at no cost to homeowners. Local ordinance banned lead pipes in 1960. However, lead water service was not banned nationally by the U.S. EPA until 1986. Beginning in 2024, the Illinois EPA will require all municipalities to establish annual lead service replacement plans in an effort to eradicate lead infrastructure.

Naperville is committed to providing clean, safe, and reliable drinking water to all customers and is taking an aggressive approach to replace lead service lines well in advance of IEPA deadlines. The City regularly tests its drinking water to ensure water quality meets or exceeds all parameters.

If you believe your property may have lead or galvanized steel service lines and the Water Utility has not yet contacted you, please email leadreplacements@naperville.il.us to request an assessment. For more information on lead service lines, visit the Lead Service Line Replacement FAQs or the Water Quality webpage.



99.40%

of 42,000+ parcels are lead-free

205

lead service lines remain

galvanized service lines remain

unconfirmed parcels

Water Service Status



LEAD SERVICE LINE REPLACED

LEAD SERVICE LINE PRESENT

GALVANIZED IN NEED OF REPLACEMENT

UNKNOWN

