

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME Reuss, George House

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Historic photograph on page 39 of NAPERVILLE HOMECOMING. According to Naperville Heritage Society brochure, Reuss was a banker and clothing manufacturer. According to article in The Naperville Sun (2/6/1998), the house had been converted to a six-flat before the renovation back to single family in 1998. 1970s photo of house in IHSS.

PERMITS

LANDSCAPE Northeast corner of Loomis and Chicago; front and west sidewalks; rear driveway; wrought iron fence; mature trees

COA DATES 11/22/2013

COA DECISION COA #13-4506 - In-kind garage door replacement (approved 11/25/2013)

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA

PREPARER Lara Ramsey

SURVEYDATE 11/17/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE



Work Completed Without COA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	White House
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on north side of residential street; front sidewalk; west side alley; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA

--

PREPARER Lara Ramsey

SURVEYDATE 11/15/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northwest corner of Chicago and Sleight; front and east sidewalks; rear driveway; wood picket fence; similar setbacks; mature trees
COA DATES	
COA DECISION	
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	Multi-directional siding at base of front façade replaced with board siding



Work Completed Without COA

Solar panels on east slope of roof near southeast corner and on east slope of roof on rear bay

PREPARER	Lara Ramsey	SURVEYDATE	11/15/2025
ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE SURVEY UPDATE

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

ARCHITECT

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATES

COA DECISION

COA Compliance Notes

COA Work Not Completed

Work Not Requiring COA



Work Completed Without COA

PREPARER

ORGANIZATION

SURVEYDATE

SURVEYAREA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR ROOF TYPE

DATE SOURCE ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	
ARCHITECT	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Northwest corner of Chicago and Wright; front and east sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees
COA DATES	11/30/2022
COA DECISION	COA #0144-2022 - Replacement of front porch stone stairs, maintaining existing wood handrails (approved 12/2/2022)
COA Compliance Notes	
COA Work Not Completed	
Work Not Requiring COA	



Work Completed Without COA	
-----------------------------------	--

PREPARER Lara Ramsey

SURVEYDATE 11/17/2025

ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA NAPERVILLE SURVEY UPDATE