

STREET #	211
DIRECTION	N
STREET	WRIGHT
SUFFIX	ST
PIN	0818140009
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	CURRENT FUNCTION	Domestic - multiple dwelling
CONDITION	Good/Fair	HISTORIC FUNCTION	Domestic - single dwelling
INTEGRITY	major alterations and/or addition(s)	REASON for SIGNIFICANCE	
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	No Style	PLAN	rectangular
DETAILS		NO OF STORIES	2.5
BEGINYEAR	c. 1900	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Parged/concrete
WALL MATERIAL (current)	Vinyl	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1
SIGNIFICANT FEATURES			
ALTERATIONS	Original house obscured by 2 story front addition (my have originally been 2-story porch addition that was enclosed); vinyl siding; replacement vinyl windows in original opening on side elevations		

HISTORIC INFORMATION

**HISTORIC
NAME**

**COMMON
NAME**

COST

ARCHITECT

ARCHITECT2

BUILDER

**ARCHITECT
SOURCE**

**HISTORIC
INFO**

PERMITS

LANDSCAPE

Midblock on west side of residential
street; front sidewalk; rear alley;
similar setbacks; mature trees

COA DATE

**COA
DECISION**

PREPARER

**PREPARER
ORGANIZATION**

SURVEYDATE

SURVEYAREA

211 N WRIGHT



**DIGITAL
PHOTO ID**

\\images\\wright21
1n.jpg

**DIGITAL
PHOTO ID3**

\\images\\wright211n(3
) .jpg

**DIGITAL
PHOTO ID2**

\\images\\wright21
1n(2).jpg

**DIGITAL
PHOTOID4**

\\images\\wright211n(4
) .jpg