

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

| | | | |
|------------------------------|--|-----------------|---|
| ARCHITECTURAL CLASSIFICATION | <input type="text" value="Greek Revival"/> | PLAN | <input type="text" value="rectangular"/> |
| DETAILS | <input type="text"/> | NO OF STORIES | <input type="text" value="2"/> |
| BEGINYEAR | <input type="text" value="c. 1865"/> | ROOF TYPE | <input type="text" value="Front gable"/> |
| OTHER YEAR | <input type="text"/> | ROOF MATERIAL | <input type="text" value="Asphalt - shingle"/> |
| DATESOURCE | <input type="text" value="Surveyor"/> | FOUNDATION | <input type="text" value="Brick"/> |
| WALL MATERIAL (current) | <input type="text" value="Wood"/> | PORCH | <input type="text" value="Front entry"/> |
| WALL MATERIAL 2 (current) | <input type="text"/> | WINDOW MATERIAL | <input type="text" value="Wood"/> |
| WALL MATERIAL (original) | <input type="text" value="Wood"/> | WINDOW MATERIAL | <input type="text" value="Vinyl"/> |
| WALL MATERIAL 2 (original) | <input type="text"/> | WINDOW TYPE | <input type="text" value="double hung/fixed/awning"/> |
| | | WINDOW CONFIG | <input type="text" value="6/6; 1-light"/> |
| SIGNIFICANT FEATURES | <input type="text" value="Front gable with cornice returns; historic 6/6 wood windows; front gable entry porch roof with cornice returns; multi-light sidelights and transom at entry; classical lintels on windows"/> | | |
| ALTERATIONS | <input #"="" type="text" value="One story north sun porch addition (not historic); fixed shutters; replacement columns and base on porch (not historic); first story window bay addition (south side, historic); two story rear addition; replacement brick foundation Replace escape window (admin. approved COA#11-4104)"/> | | |

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southeast corner of Benton and Columbia; front and north sidewalks; rear driveway; rear picket fence; similar setbacks; mature trees

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4