

STREET # 140  
 DIRECTION N  
 STREET WRIGHT  
 SUFFIX ST  
 PIN 0818309002  
 LOCAL SIGNIFICANCE RATING C  
 POTENTIAL IND NR? (Y or N) N  
 Contributing to a NR DISTRICT? C  
 Contributing secondary structure? -  
 Listed on existing SURVEY? Local District; NR District



**GENERAL INFORMATION**

CATEGORY building CURRENT FUNCTION Education - school  
 CONDITION excellent HISTORIC FUNCTION Education - college  
 INTEGRITY not altered REASON for SIGNIFICANCE  
 SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION Classrooms-Contemporary PLAN L  
 DETAILS NO OF STORIES 3  
 BEGINYEAR c. 1950 ROOF TYPE Multi-gable  
 OTHER YEAR ROOF MATERIAL Ceramic Tile  
 DATESOURCE Surveyor FOUNDATION Concrete  
 WALL MATERIAL (current) Brick PORCH -  
 WALL MATERIAL 2 (current) WINDOW MATERIAL Metal  
 WALL MATERIAL (original) Brick WINDOW MATERIAL  
 WALL MATERIAL 2 (original) WINDOW TYPE casement  
 WINDOW CONFIG 1-light  
 SIGNIFICANT FEATURES L-shaped massing; concrete panels at entry on gable bay  
 ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTO ID4**

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

SIGNIFICANT FEATURES  WINDOW CONFIG

ALTERATIONS



**HISTORIC INFORMATION**

**HISTORIC NAME** Kroehler, P.E., Carriage House

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO** Was originally carriage house for the P. E. Kroehler House

**PERMITS**

**LANDSCAPE** Midblock on south side of residential street; parking lot to east; mature trees

**COA DATE**

**COA DECISION**

**PREPARER** Lara Ramsey

**PREPARER ORGANIZATION** GRANACKI HISTORIC CONSULTANTS

**SURVEYDATE** 11/7/2007

**SURVEYAREA** NAPERVILLE



<b>DIGITAL PHOTO ID</b>	\Images\wright148n(1).jpg	<b>DIGITAL PHOTO ID3</b>	\Images\wright148n(3).jpg
<b>DIGITAL PHOTO ID2</b>	\Images\wright148n(2).jpg	<b>DIGITAL PHOTO ID4</b>	\Images\wright148n(4).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



**GENERAL INFORMATION**

CATEGORY  CURRENT FUNCTION

CONDITION  HISTORIC FUNCTION

INTEGRITY  REASON for SIGNIFICANCE

SECONDARY STRUCTURE

**ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION  PLAN

DETAILS  NO OF STORIES

BEGINYEAR  ROOF TYPE

OTHER YEAR  ROOF MATERIAL

DATESOURCE  FOUNDATION

WALL MATERIAL (current)  PORCH

WALL MATERIAL 2 (current)  WINDOW MATERIAL

WALL MATERIAL (original)  WINDOW MATERIAL

WALL MATERIAL 2 (original)  WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

**HISTORIC INFORMATION**

**HISTORIC NAME**

**COMMON NAME**

**COST**

**ARCHITECT**

**ARCHITECT2**

**BUILDER**

**ARCHITECT SOURCE**

**HISTORIC INFO**

**PERMITS**

**LANDSCAPE**

**COA DATE**

**COA DECISION**

**PREPARER**

**PREPARER ORGANIZATION**

**SURVEYDATE**

**SURVEYAREA**



**DIGITAL PHOTO ID**

**DIGITAL PHOTO ID3**

**DIGITAL PHOTO ID2**

**DIGITAL PHOTOID4**