

STREET #	214
DIRECTION	
STREET	NORTH
SUFFIX	AV
PIN	0818132012
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	fair	REASON for SIGNIFICANCE	
INTEGRITY	major alterations and/or addition(s)		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	L-Form	PLAN	Rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1900	ROOF TYPE	Combination
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor/Sanborn maps	FOUNDATION	Stone/concrete - block
WALL MATERIAL (current)	Aluminum	PORCH	Front entry
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light

SIGNIFICANT FEATURES	Front gable bay and recessed side gable wing (now obscured by later addition)
----------------------	---

ALTERATIONS	Two-story addition in front of original west wing (c. 1970); Aluminum siding; replacement front entry porch (non-historic); replacement front door (non-historic); replacement 1/1 windows in slightly downsized openings; fixed shutters; rear porch addition (non-historic). Post-2007 -- no changes.
-------------	---

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO			
PERMITS			
LANDSCAPE	Midblock on south side of residential street; front sidewalk; side driveway (partial); similar setbacks; mature trees		
COA DATE			
COA DECISION			
☐ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

--

\\images\\25_North

\\images\\25_NorthA

\\images\\25_NorthA

\\images\\25_NorthA

STREET #	218
DIRECTION	
STREET	NORTH
SUFFIX	AV
PIN	0818132013
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	Rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1900	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Stone
WALL MATERIAL (current)	Vinyl	PORCH	Full front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Wood/leaded glass
WALL MATERIAL 2 (original)		WINDOW TYPE	Double & single hung; cas
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Broad front gable roof and rectangular massing; single hung leaded glass and leaded glass casement (damaged) windows under porch; hipped roof full front porch with round columns on concrete block piers		
ALTERATIONS	Replacement siding (not historic); vinyl replacement windows in original openings; fixed shutters; replacement door (not historic); replacement railings and columns on porch (ca. 1910). Post-2007 -- replacement front door.		

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO			
PERMITS			
LANDSCAPE	Midblock on south side of residential street; front sidewalk; east side alley; similar setbacks; mature trees		
COA DATE			
COA DECISION			
☐ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	11/30/2007
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE



☒ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

replacement front door.

\\images\25_North

\\images\25_NorthA

\\images\25_NorthA

\\images\25_NorthA

STREET #	151-163
DIRECTION	
STREET	SCHOOL
SUFFIX	ST
PIN	0818129011
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - multiple dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Townhouses-Mansard	PLAN	Rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1975	ROOF TYPE	Mansard
OTHER YEAR		ROOF MATERIAL	Wood shingle
DATESOURCE	Surveyor/Aerial Maps	FOUNDATION	Concrete
WALL MATERIAL (current)	Wood - shingle/Stone	PORCH	
WALL MATERIAL 2 (current)	Wood - vertical board	WINDOW MATERIAL	Aluminum
WALL MATERIAL (original)	Wood - shingle/Stone	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Wood - vertical board	WINDOW TYPE	sliding
		WINDOW CONFIG	1-1
SIGNIFICANT FEATURES	Mansard roof that encompasses second story; regularly spaced dormers with shed roofs; rock-face stone and brick at first story; sliding windows in original openings.		
ALTERATIONS	Post-2007 -- some entry doors appear to have been replaced.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Scho

\\images\25_School

\\images\25_School

\\images\25_School

STREET #	309
DIRECTION	
STREET	SCHOOL
SUFFIX	ST
PIN	0818134003 & 004
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Education - college
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	not altered		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Contemporary	PLAN	irregular
DETAILS	Brutalist	NO OF STORIES	2
BEGINYEAR	1967	ROOF TYPE	Flat
OTHER YEAR		ROOF MATERIAL	Not visible
DATESOURCE	Date Plaque	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)	Concrete	WINDOW MATERIAL	Metal
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Concrete	WINDOW TYPE	Fixed/awning
		WINDOW CONFIG	1-light
SIGNIFICANT FEATURES	Flat roof with concrete parapet (formwork on concrete is visible); multi-tonal red brick exterior walls with concrete horizontal banding; large west volume with no fenestration above raised basement level; slight taller entry bay on south elevation with cantilevered canopy over entry doors; two-story east volume with multi-light window at 2nd story; unfenestated west elevation (facing Brainard St) divided by recessed entry bay with cantilevered canopy over doors and glazing above		
ALTERATIONS	Basement window boarded up on south elevation.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**


COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Scho

\\images\25_School

\\images\25_School

\\images\25_School

STREET #	320
DIRECTION	
STREET	SCHOOL
SUFFIX	ST
PIN	0818306001
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Education - library
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	not altered		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	International Style	PLAN	irregular
DETAILS		NO OF STORIES	1+bsm
BEGINYEAR	1954	ROOF TYPE	Flat
OTHER YEAR		ROOF MATERIAL	Not visible
DATESOURCE	Surveyor	FOUNDATION	concrete
WALL MATERIAL (current)	Brick	PORCH	-
WALL MATERIAL 2 (current)	Concrete	WINDOW MATERIAL	Aluminum
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)	Concrete	WINDOW TYPE	fixed
		WINDOW CONFIG	multi-light
SIGNIFICANT FEATURES	Flat roof and geometric massing; broad, regular bays separated brick square piers; 1 story entry bay with flat roof		
ALTERATIONS	According to NCC, building was renovated in 2005. Post-2007 -- replacement windows in original openings (configuration differs from windows present on building during 2007 survey); replacement windows		

HISTORIC INFORMATION

HISTORIC NAME			
COMMON NAME			
COST			
ARCHITECT			
ARCHITECT2			
BUILDER			
ARCHITECT SOURCE			
HISTORIC INFO			
PERMITS			
LANDSCAPE	Southeast corner of School and Brainard; front and west sidewalks; building is at north end of main campus block; mature trees		
COA DATE	7/9/2018		
COA DECISION	COA #18-2731 - In-kind replacement of doors and windows - windows will be divided (approved 7/13/2018)		
☒ IN COMPLIANCE WITH COA?			
COA COMPLIANCE NOTES:			
PREPARER	Lara Ramsey	SURVEYDATE	11/20/2025
PREPARER ORGANIZATION	RAMSEY HISTORIC CONSULTANTS	SURVEYAREA	NAPERVILLE HISTORIC DISTRICT



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

--

\\Images\\25_Scho
\\Images\\25_School
\\Images\\25_School
\\Images\\25_School

STREET #	329
DIRECTION	
STREET	SCHOOL
SUFFIX	ST
PIN	0818134007
LOCAL SIGNIFICANCE RATING	S
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Education - college
CONDITION	excellent	REASON for SIGNIFICANCE	Despite the replacement windows and east side addition, this building remains architecturally significant.
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gothic Revival	PLAN	irregular
DETAILS		NO OF STORIES	2
BEGINYEAR	1912	ROOF TYPE	Gable on hip
OTHER YEAR	2006	ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Plaque	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Brick	PORCH	-
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum
WALL MATERIAL (original)	Brick	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	3/1; multi/1
SIGNIFICANT FEATURES	Hipped roof w/ exposed rafter tails; front gable bay w/ stone detailing; center entry w/ elaborate stone surround & large flattened pointed arch window opening above; 2nd story segmental arch window openings w/ label molds & brick spandrel panels		
ALTERATIONS	Replacement windows in orig. openings; replacement front entry doors & transoms; 2 story rear/west addition (historic); 1 story east addition (non-historic); replacement multi-light window over entry; front entry stairs removed & N entry modified (2006). Post-2007 -- no changes.		

HISTORIC INFORMATION

HISTORIC NAME Kiekhofer Hall

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Building featured in Naperville Heritage Housewalk brochure. See continuation sheet.

PERMITS

LANDSCAPE Northwest corner of Loomis and School; front and east sidewalks; west side parking lot

COA DATE

COA DECISION

☐ IN COMPLIANCE WITH COA?


COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



☐ ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\Images\\25_Scho

\\Images\\25_School

\\Images\\25_School

\\Images\\25_School

STREET #	418
DIRECTION	
STREET	SCHOOL
SUFFIX	ST
PIN	0818138002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	major alterations and/or addition(s)		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gable Front	PLAN	rectangular
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1925	ROOF TYPE	Front gable
OTHER YEAR	c. 1940	ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor/Sanborn maps	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Fiber cement board	PORCH	-
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	1/1
SIGNIFICANT FEATURES	Front gable roof and rectangular massing		
ALTERATIONS	Replacement windows (possibly in altered openings first story of front façade); 2 story rear addition connecting building to existing garage (c. 1940). Post-2007 -- replacement siding; gable-roof canopy over entrance replaced with full-width front porch with hipped roof, square columns, and railing; addition to garage at east end; replacement front door at west entry; ramp and steps to east entry and new entry on garage addition.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO The 1926 Sanborn map shows this 2-story building as a store, with an attached garage at the rear of the lot. A 2-story addition connecting the store building and garage were constructed sometime between 1926 and 1949.

PERMITS

LANDSCAPE Midblock on south side of residential street; front sidewalk; east side alley; mature trees

COA DATE 9/24/2015; 10/14/2019; 4/16/2020

COA DECISION COA #15-2157 - Renovation of and addition to attached garage (approved by HPC 9/24/2015); COA #19-3978 - In-kind door, siding, shingle replacement. Removal of chimney and shutters (approved 10/18/2019); COA #19-3978 - field change for a patio, ramp, and sidewalk changes (approved 4/17/2020)

☒ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Scho

\\images\25_School

\\images\25_School

\\images\25_School

11/20/2025

NAPERVILLE HISTORIC DISTRICT

STREET #	421
DIRECTION	
STREET	SCHOOL
SUFFIX	ST
PIN	0818137008
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	C
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	Minor alterations and addition(s)		
SECONDARY STRUCTURE	Detached garage		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Gabled Ell Cottage	PLAN	L
DETAILS		NO OF STORIES	2
BEGINYEAR	c. 1915	ROOF TYPE	Front gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor/Sanborn Maps	FOUNDATION	Parged
WALL MATERIAL (current)	Aluminum	PORCH	-
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	Wood
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung/fixed
		WINDOW CONFIG	1/1; 1-light
SIGNIFICANT FEATURES	Front gable roof with cornice returns; 2 story east side gable ell		
ALTERATIONS	Aluminum siding; replacement 1/1 vinyl windows in original openings; wood single light windows in altered openings; new entry and surround; glass block window on E side of front gable bay; E. side entry addition; 1 story E. addition; bay on W. side; vergeboard added in gable peak. Post-2007 -- aluminum siding either painted or replaced; wraparound front porch with hip/shed roof, square columns and open railings, and triangular pediment above porch entrance.		

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps from the early 20th century show that the house originally featured a wraparound front porch that was removed sometime after 1954.

PERMITS

LANDSCAPE Midblock on north side of residential street; front sidewalk; west side alley; similar setbacks; mature trees

COA DATE 8/5/2019 (application date)

COA DECISION Application for COA dated 8/5/2019 for new wraparound front porch with hip/shed roof, triangular pediment at entrance, square columns and open railings. Drawings show porch with decorative corner detailing at columns, which were not included when built.

☒ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE

SURVEYAREA



☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

\\images\25_Scho

\\images\25_School

\\images\25_School

\\images\25_School

11/20/2025

NAPERVILLE HISTORIC DISTRICT

STREET #	516
DIRECTION	
STREET	SCHOOL
SUFFIX	ST
PIN	0818141002
LOCAL SIGNIFICANCE RATING	C
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	C
Contributing secondary structure?	-
Listed on existing SURVEY?	IHSS (O); Local District; NR

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - single dwelling
CONDITION	good	REASON for SIGNIFICANCE	
INTEGRITY	minor alterations and addition(s)		
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	L-Form	PLAN	L
DETAILS	Italianate	NO OF STORIES	2.5
BEGINYEAR	c. 1875	ROOF TYPE	Multi-gable
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	Surveyor	FOUNDATION	Concrete - block
WALL MATERIAL (current)	Aluminum	PORCH	Front entry & front
WALL MATERIAL 2 (current)		WINDOW MATERIAL	Aluminum/vinyl
WALL MATERIAL (original)	Wood	WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	double hung
		WINDOW CONFIG	6/6

SIGNIFICANT FEATURES	Two story front gable bay intersected by two-story gable-roof west wing; historic porch at west wing.
----------------------	---

ALTERATIONS	Aluminum siding; original window hoods removed when re-sided (see IHSS photo); hipped-roof entry porch at entry on east bay (built sometime between 1954 and 1974); replacement doors (1940s); 1 story rear addition. Post-2007 -- historic 4/4 wood windows replaced with 6/6 Aluminum/vinyl replacement windows in existing openings.
-------------	---

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Building does not appear on Sanborn maps at this location until 1949, but massing, roofline, and fenestration patterns are consistent with late 19th century residence, suggesting that the building may have been moved from another location. IHSS photo from the 1970s shows the house with Italianate-style window hoods. More research is needed to confirm if the house was moved.

PERMITS

LANDSCAPE Midblock on south side of residential street; house on slight rise with retaining wall; east side alley; similar setbacks; mature trees; front sidewalk

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**


COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

SURVEYDATE

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



☒ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

historic 4/4 wood windows replaced with 6/6 Aluminum/vinyl replacement windows in existing openings.

\\images\\25_Scho

\\images\\25_Schoo

\\images\\25_School

\\images\\25_School

STREET #	610-616
DIRECTION	
STREET	SCHOOL
SUFFIX	ST
PIN	
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	
Listed on existing SURVEY?	

GENERAL INFORMATION

CATEGORY	site	HISTORIC FUNCTION	
CONDITION		REASON for SIGNIFICANCE	
INTEGRITY			
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION		PLAN	
DETAILS		NO OF STORIES	
BEGINYEAR		ROOF TYPE	
OTHER YEAR		ROOF MATERIAL	
DATESOURCE		FOUNDATION	
WALL MATERIAL (current)		PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	
WALL MATERIAL (original)		WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	
		WINDOW CONFIG	
SIGNIFICANT FEATURES			
ALTERATIONS			

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA

STREET #	620-624
DIRECTION	
STREET	SCHOOL
SUFFIX	ST
PIN	0818309002
LOCAL SIGNIFICANCE RATING	NC
POTENTIAL IND NR? (Y or N)	N
Contributing to a NR DISTRICT?	NC
Contributing secondary structure?	-
Listed on existing SURVEY?	Local District; NR District

**GENERAL INFORMATION**

CATEGORY	building	HISTORIC FUNCTION	Domestic - multiple dwelling
CONDITION	excellent	REASON for SIGNIFICANCE	
INTEGRITY	under construction		
SECONDARY STRUCTURE	-		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	Row Houses - New Traditional	PLAN	rectangular
DETAILS		NO OF STORIES	3.5
BEGINYEAR	2026	ROOF TYPE	Combination
OTHER YEAR		ROOF MATERIAL	Asphalt - shingle
DATESOURCE	surveyor	FOUNDATION	Concrete
WALL MATERIAL (current)	Brick	PORCH	Front entry
WALL MATERIAL 2 (current)	Cast Stone	WINDOW MATERIAL	Aluminum
WALL MATERIAL (original)		WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	Double hung; other
		WINDOW CONFIG	multi-light
SIGNIFICANT FEATURES			
ALTERATIONS			

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

☐ **IN COMPLIANCE WITH COA?**

COA COMPLIANCE NOTES:

☐ **ELIGIBLE WORK COMPLETED WITHOUT COA?**

NOTES ON WORK:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA

\\images\25_Scho