

STREET # 140
 DIRECTION N
 STREET WRIGHT
 SUFFIX ST
 PIN 0818309002
 LOCAL SIGNIFICANCE RATING C
 POTENTIAL IND NR? (Y or N) N
 Contributing to a NR DISTRICT? C
 Contributing secondary structure? -
 Listed on existing SURVEY? Local District; NR District



GENERAL INFORMATION

CATEGORY building CURRENT FUNCTION Education - school
 CONDITION excellent HISTORIC FUNCTION Education - college
 INTEGRITY not altered REASON for SIGNIFICANCE
 SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Classrooms-Contemporary PLAN L
 DETAILS NO OF STORIES 3
 BEGINYEAR c. 1950 ROOF TYPE Multi-gable
 OTHER YEAR ROOF MATERIAL Ceramic Tile
 DATESOURCE Surveyor FOUNDATION Concrete
 PORCH -
 WALL MATERIAL (current) Brick WINDOW MATERIAL Metal
 WALL MATERIAL 2 (current) WINDOW MATERIAL
 WALL MATERIAL (original) Brick WINDOW TYPE casement
 WALL MATERIAL 2 (original) WINDOW CONFIG 1-light
 SIGNIFICANT FEATURES L-shaped massing; concrete panels at entry on gable bay
 ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME Kroehler, P.E., Carriage House

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Was originally carriage house for the P. E. Kroehler House

PERMITS

LANDSCAPE Midblock on south side of residential street; parking lot to east; mature trees

COA DATE

COA DECISION

PREPARER Lara Ramsey

PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS

SURVEYDATE 11/7/2007

SURVEYAREA NAPERVILLE



DIGITAL PHOTO ID

\\images\wright148n(3).jpg

DIGITAL PHOTO ID3

\\images\wright148n(4).jpg

DIGITAL PHOTO ID2

\\images\wright148n(2).jpg

DIGITAL PHOTO ID4

\\images\wright148n(3).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4