

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE


COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTO ID4

STREET # 148
 DIRECTION N
 STREET WRIGHT
 SUFFIX ST
 PIN 0818309002
 LOCAL SIGNIFICANCE RATING C
 POTENTIAL IND NR? (Y or N) N
 Contributing to a NR DISTRICT? C
 Contributing secondary structure? -
 Listed on existing SURVEY? Local District; NR District



GENERAL INFORMATION

CATEGORY building CURRENT FUNCTION Domestic - secondary structure
 CONDITION good HISTORIC FUNCTION Domestic - secondary structure
 INTEGRITY minor alterations and addition(s) REASON for SIGNIFICANCE
 SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Garage PLAN rectangular
 DETAILS NO OF STORIES 2
 BEGINYEAR c. 1910 ROOF TYPE Hipped
 OTHER YEAR ROOF MATERIAL Ceramic Tile
 DATESOURCE Surveyor FOUNDATION Concrete
 WALL MATERIAL (current) Brick PORCH
 WALL MATERIAL 2 (current) WINDOW MATERIAL Wood
 WALL MATERIAL (original) Brick WINDOW MATERIAL
 WALL MATERIAL 2 (original) WINDOW TYPE double hung/awning
 WINDOW CONFIG multi-light
 SIGNIFICANT FEATURES Hipped roof with ceramic tile; historic multi-light double hung and awning windows; two-bay garage doors
 ALTERATIONS Replacement garage doors; one story north addition (historic)--windows in addition boarded up

HISTORIC INFORMATION

HISTORIC NAME Kroehler, P.E., Carriage House

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Was originally carriage house for the P. E. Kroehler House

PERMITS

LANDSCAPE Midblock on south side of residential street; parking lot to east; mature trees

COA DATE

COA DECISION

PREPARER Lara Ramsey

PREPARER ORGANIZATION GRANACKI HISTORIC CONSULTANTS

SURVEYDATE 11/7/2007

SURVEYAREA NAPERVILLE



DIGITAL PHOTO ID \Images\wright148n(3).jpg

DIGITAL PHOTO ID3 \Images\wright148n(3).jpg

DIGITAL PHOTO ID2 \Images\wright148n(2).jpg

DIGITAL PHOTO ID4 \Images\wright148n(4).jpg

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY CURRENT FUNCTION

CONDITION HISTORIC FUNCTION

INTEGRITY REASON for SIGNIFICANCE

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



DIGITAL PHOTO ID

DIGITAL PHOTO ID3

DIGITAL PHOTO ID2

DIGITAL PHOTOID4