


Naperville Metra Station Entrances Survey



*No ADA door openers or push buttons on **west** side building exit*



Mag Lock "Push To Exit Button" missing



ADA push button approx. 6' from door on south side of building entrance: within regulations but not very practical



*No ADA door openers or push buttons on **east** side building exit*