

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on south side of residential street; front sidewalk; side driveway (partial); similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

SURVEYDATE

SURVEYAREA

\\images\25_North

\\images\25_NorthA

\\images\25_NorthA

\\images\25_NorthA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONSOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Midblock on south side of residential street; front sidewalk; east side alley; similar setbacks; mature trees

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: replacement front door.

\\images\25_North

\\images\25_NorthA

\\images\25_NorthA

\\images\25_NorthA

STREET # 151-163
 DIRECTION
 STREET SCHOOL
 SUFFIX ST
 PIN 0818129011
 LOCAL SIGNIFICANCE RATING C
 POTENTIAL IND NR? (Y or N) N
 Contributing to a NR DISTRICT? C
 Contributing secondary structure? -
 Listed on existing SURVEY? Local District; NR District



GENERAL INFORMATION

CATEGORY building HISTORIC FUNCTION Domestic - multiple dwelling
 CONDITION good REASON for SIGNIFICANCE
 INTEGRITY minor alterations
 SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION Townhouses-Mansard PLAN Rectangular
 DETAILS NO OF STORIES 2
 BEGINYEAR c. 1975 ROOF TYPE Mansard
 OTHER YEAR ROOF MATERIAL Wood shingle
 DATESOURCE Surveyor/Aerial Maps FOUNDATION Concrete
 PORCH
 WALL MATERIAL (current) Wood - shingle/Stone WINDOW MATERIAL Aluminum
 WALL MATERIAL 2 (current) Wood - vertical board WINDOW MATERIAL
 WALL MATERIAL (original) Wood - shingle/Stone WINDOW TYPE sliding
 WALL MATERIAL 2 (original) Wood - vertical board WINDOW CONFIG 1-1
 SIGNIFICANT FEATURES Mansard roof that encompasses second story; regularly spaced dormers with shed roofs; rock-face stone and brick at first story; sliding windows in original openings.
 ALTERATIONS Post-2007 -- some entry doors appear to have been replaced.

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA

\\images\25_Scho

\\images\25_School

\\images\25_School

\\images\25_School

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATE SOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?


COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Scho
 \\images\25_School
 \\images\25_School
 \\images\25_School

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE Southeast corner of School and Brainard; front and west sidewalks; building is at north end of main campus block; mature trees

COA DATE 7/9/2018

COA DECISION COA #18-2731 - In-kind replacement of doors and windows - windows will be divided (approved 7/13/2018)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

SURVEYDATE

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

11/20/2025

NAPERVILLE HISTORIC DISTRICT

\\images\25_Scho

\\images\25_School

\\images\25_School

\\images\25_School

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR ROOF TYPE

DATESOURCE ROOF MATERIAL

WALL MATERIAL (current) FOUNDATION

WALL MATERIAL 2 (current)

WALL MATERIAL (original) PORCH

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Building featured in Naperville Heritage Housewalk brochure. See continuation sheet.

PERMITS

LANDSCAPE Northwest corner of Loomis and School; front and east sidewalks; west side parking lot

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?


COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Scho

\\images\25_School

\\images\25_School

\\images\25_School

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR ROOF TYPE

DATESOURCE ROOF MATERIAL

FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO The 1926 Sanborn map shows this 2-story building as a store, with an attached garage at the rear of the lot. A 2-story addition connecting the store building and garage were constructed sometime between 1926 and 1949.

PERMITS

LANDSCAPE Midblock on south side of residential street; front sidewalk; east side alley; mature trees

COA DATE 9/24/2015; 10/14/2019; 4/16/2020

COA DECISION COA #15-2157 - Renovation of and addition to attached garage (approved by HPC 9/24/2015); COA #19-3978 - In-kind door, siding, shingle replacement. Removal of chimney and shutters (approved 10/18/2019); COA #19-3978 - field change for a patio, ramp, and sidewalk changes (approved 4/17/2020)

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER Lara Ramsey

PREPARER ORGANIZATION RAMSEY HISTORIC CONSULTANTS

SURVEYDATE 11/20/2025

SURVEYAREA NAPERVILLE HISTORIC DISTRICT



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Scho
 \\images\25_School
 \\images\25_School
 \\images\25_School

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original) WINDOW TYPE

SIGNIFICANT FEATURES WINDOW CONFIG

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Sanborn maps from the early 20th century show that the house originally featured a wraparound front porch that was removed sometime after 1954.

PERMITS

LANDSCAPE Midblock on north side of residential street; front sidewalk; west side alley; similar setbacks; mature trees

COA DATE 8/5/2019 (application date)

COA DECISION Application for COA dated 8/5/2019 for new wraparound front porch with hip/shed roof, triangular pediment at entrance, square columns and open railings. Drawings show porch with decorative corner detailing at columns, which were not included when built.

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

\\images\25_Scho
 \\images\25_School
 \\images\25_School
 \\images\25_School

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS NO OF STORIES

BEGINYEAR ROOF TYPE

OTHER YEAR

ROOF MATERIAL

DATESOURCE FOUNDATION

WALL MATERIAL (current) PORCH

WALL MATERIAL 2 (current)

WALL MATERIAL (original) WINDOW MATERIAL

WALL MATERIAL 2 (original)

WINDOW MATERIAL

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO Building does not appear on Sanborn maps at this location until 1949, but massing, roofline, and fenestration patterns are consistent with late 19th century residence, suggesting that the building may have been moved from another location. IHSS photo from the 1970s shows the house with Italianate-style window hoods. More research is needed to confirm if the house was moved.

PERMITS

LANDSCAPE Midblock on south side of residential street; house on slight rise with retaining wall; east side alley; similar setbacks; mature trees; front sidewalk

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

PREPARER

PREPARER ORGANIZATION

SURVEYDATE

SURVEYAREA



ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK: historic 4/4 wood windows replaced with 6/6 Aluminum/vinyl replacement windows in existing openings.

\\images\25_Scho

\\imagest\25_Schoo

\\images\25_School

\\images\25_School

STREET #	610-616	
DIRECTION		
STREET	SCHOOL	
SUFFIX	ST	
PIN		
LOCAL SIGNIFICANCE RATING	NC	
POTENTIAL IND NR? (Y or N)	N	
Contributing to a NR DISTRICT?	NC	
Contributing secondary structure?		
Listed on existing SURVEY?		

GENERAL INFORMATION

CATEGORY	site	HISTORIC FUNCTION	
CONDITION		REASON for SIGNIFICANCE	
INTEGRITY			
SECONDARY STRUCTURE			

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION		PLAN	
DETAILS		NO OF STORIES	
BEGINYEAR		ROOF TYPE	
OTHER YEAR		ROOF MATERIAL	
DATESOURCE		FOUNDATION	
WALL MATERIAL (current)		PORCH	
WALL MATERIAL 2 (current)		WINDOW MATERIAL	
WALL MATERIAL (original)		WINDOW MATERIAL	
WALL MATERIAL 2 (original)		WINDOW TYPE	
SIGNIFICANT FEATURES			
ALTERATIONS			

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA

STREET #

DIRECTION

STREET

SUFFIX

PIN

LOCAL SIGNIFICANCE RATING

POTENTIAL IND NR? (Y or N)

Contributing to a NR DISTRICT?

Contributing secondary structure?

Listed on existing SURVEY?



GENERAL INFORMATION

CATEGORY HISTORIC FUNCTION

CONDITION REASON for SIGNIFICANCE

INTEGRITY

SECONDARY STRUCTURE

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION PLAN

DETAILS

BEGINYEAR NO OF STORIES

OTHER YEAR

ROOF TYPE

ROOF MATERIAL

FOUNDATIONS

PORCH

WALL MATERIAL (current) WINDOW MATERIAL

WALL MATERIAL 2 (current) WINDOW MATERIAL

WALL MATERIAL (original)

WALL MATERIAL 2 (original)

WINDOW TYPE

WINDOW CONFIG

SIGNIFICANT FEATURES

ALTERATIONS

HISTORIC INFORMATION

HISTORIC NAME

COMMON NAME

COST

ARCHITECT

ARCHITECT2

BUILDER

ARCHITECT SOURCE

HISTORIC INFO

PERMITS

LANDSCAPE

COA DATE

COA DECISION

IN COMPLIANCE WITH COA?

COA COMPLIANCE NOTES:

ELIGIBLE WORK COMPLETED WITHOUT COA?

NOTES ON WORK:

PREPARER

SURVEYDATE

PREPARER ORGANIZATION

SURVEYAREA

\\images\25_Scho