STREET #	140			£V		
DIRECTION	N		Mr. 1800	DA	THE STATE OF THE S	
STREET	WRIGHT		The Market	<b>新</b>	P AT A STATE OF THE STATE OF TH	
SUFFIX	ST			12	OF SURE	
PIN	0818309002		1		外人	and the second
POTENTIAL IND	C			mi am ii m am ii m am ii		
Contributing to a	С	- NR District				
			<b>GENERAL IN</b>	NFORM	ATION	
<b>CATEGORY</b> bui	ilding		CURRENT FUN	CTION E	Education - school	
CONDITION	cellent		HISTORIC FUN	CTION E	Education - college	
INTEGRITY not	t altered		REASON for			
SIGNFICANCE SECONDARY STRUCTURE						
			ARCHITECTU	RAL DE	SCRIPTION	
ARCHITECTURAL CLASSIFICATION		s-Contemporary			PLAN	L
	Oldooroom	o contomporary			NO OF STORIES	3
DETAILS	- 4050				ROOF TYPE	Multi-gable
BEGINYEAR OTHER VEAR	c. 1950				ROOF MATERIAL	Ceramic Tile
OTHER YEAR	Curvovor				FOUNDATION	Concrete
DATESOURCE Surveyor - PORCH					-	
WALL MATERIAL (current)  WALL MATERIAL 2 (current)				WINDOW MATERIA	L Metal	
WALL MATERIAL 2 (current) WALL MATERIAL (original)  Brick  WINDOW MATERIAL						
WALL MATERIAL 2 (original)			WINDOW TYPE casement			
VVIII VIII II	2 2 (Original)				WINDOW CONFIG	1-light
SIGNIFICANT L FEATURES	-shaped massi	ng; concrete panel	ls at entry on gable b	ay		
ALTERATIONS						

#### HISTORIC INFORMATION

HISTORIC NAME	
COMMON NAME	Little Friends, Inc.
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
HISTORIC INFO	
PERMITS	
LANDSCAPE	Midblock on east side of residential street, parking lot to north; curving drive leading to another school
	building to south; mature trees
COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATI	GRANACKI HISTORIC CONSULTANTS
SURVEYDATI	E 11/7/2007
SURVEYARE	A NAPERVILLE
140 N	WRIGHT







DIGITAL PHOTO ID

DIGITAL PHOTO ID2

\lmages\wright14 DIGITAL PHOTO ID3

\lmages\wright14 DIGITAL On(2).jpg PHOTOID

PHOTOID4

\Images\wright140n(3 ).jpg

\Images\wright140n(4 ).jpg

STREET #	148					
DIRECTION	N	عفف				
STREET	WRIGHT					
SUFFIX	ST					
PIN	0818309002					
LOCAL SIGNIFICANCE RATING	C	ALC: N				
POTENTIAL IND NR? (Y or N)	N					
Contributing to a NR DISTRICT?	C					
Contributing second Listed on existing SURVEY?	Local District; NR District					
		GENERAL INFO	RMATION			
CATEGORY bu	ilding	CURRENT FUNCTIO	Domestic - secondary s	structure		
CONDITION go						
INTEGRITY mi	nor alterations and addition(s)	REASON for SIGNFICANCE				
SECONDARY STRUCTURE	SECONDARY					
		ARCHITECTURAL	DESCRIPTION			
ARCHITECTURAL CLASSIFICATION			PLAN	rectangular		
	Garage		NO OF STORIES	2		
DETAILS	- 4040		ROOF TYPE	Hipped		
BEGINYEAR OTHER VEAR	c. 1910		ROOF MATERIAL	Ceramic Tile		
OTHER YEAR DATESOURCE	Surveyor		FOUNDATION	Concrete		
WALL MATERIAL			PORCH			
			WINDOW MATERIA	AL Wood		
WALL MATERIAL 2 (current) WALL MATERIAL (original)  Brick  WINDOW MATERIAL						
WALL MATERIAL			WINDOW TYPE	double hung/awning		
	= (vigini)		WINDOW CONFIG	multi-light		
SIGNIFICANT FEATURES	dipped roof with ceramic tile; his	storic multi-light double hung	and awning windows; two-	bay garage doors		
<b>ALTERATIONS</b> F	Replacement garage doors; one	e story north addition (historic	c)windows in addition boar	rded up		

### **HISTORIC INFORMATION**

	Kroehler, P.E., Carriage House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
	s originally carriage house for the E. Kroehler House
PERMITS	
st	idblock on south side of residential reet; parking lot to east; mature ees
COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/7/2007
SURVEYAREA	NAPERVILLE
148 N WF	RIGHT





DIGITAL PHOTO ID DIGITAL PHOTO ID2 \lmages\wright14 DIGITAL PHOTO ID3

\lmages\wright14 \\ 8n(2).jpg \quad PHOTOID4

\Images\wright148n(3 ).jpg

\Images\wright148n(4 ).jpg

STREET #	126				THE STATE OF THE S	
DIRECTION	N					
STREET	WRIGHT				3	
SUFFIX	ST		76	30/	1 No. 100	
PIN	0818309002		V siles	THE RESERVE		
LOCAL SIGNIFICANCE RATING	S		В			
POTENTIAL IND NR? (Y or N)	N			*		
Contributing to a NR DISTRICT?	С				minim A	
Contributing secon	dary structure	? -		Corector Corector		
Listed on existing SURVEY?	IHSS (O); Loc	cal District; NR				
			<b>GENERAL INFO</b>	<u>ORMATION</u>		
CATEGORY bu	uilding		CURRENT FUNCTION	ON Education - school		
CONDITION go	ood		HISTORIC FUNCTION	ON Domestic - single dwelling	ng	
INTEGRITY m						
SIGNFICANCE house remains a significant structure in the district.  SECONDARY STRUCTURE						
			ARCHITECTURAI	L DESCRIPTION		
ARCHITECTURA CLASSIFICATION		•			irregular	
	Oransman			NO OF STORIES	2.5	
DETAILS	- 4045			ROOF TYPE	Side gable	
BEGINYEAR	c. 1915			ROOF MATERIAL	Asphalt - shingle	
OTHER YEAR	Cumiovor			FOUNDATION	Not visible	
DATESOURCE WALL MATERIA	Surveyor	Brick		PORCH	Wrap around	
		BIICK		WINDOW MATERIAL	L Wood	
WALL MATERIAL 2 (current)		Brick		WINDOW MATERIAL	L Glass block	
WALL MATERIAL (original) Brick WALL MATERIAL 2 (original)		BIICK		WINDOW TYPE	casement/double hung/fixe	
WALL MATERIA	L 2 (Oi igiliai)			WINDOW CONFIG	1/1; 1-light	
	Side gable roof windows	f with shed dormers	and copper gutters; wrap	around porch with square bri	ick piers; historic 1/1 wood	
		vindows in dormers; onnected with 140 N		mer; exterior stair on south s	ide; one story rear addition	

HISTO	ORIC INFORMATION
HISTORIC K	roehler, P. E. House
COMMON NAME	
COST	
ARCHITECT	
ARCHITECT2	
BUILDER	
ARCHITECT SOURCE	
INFO Lour	P. E. Kroehler was Naperville nge Factory Co.'s president nning in 1903.
PERMITS	
stre alm	dblock on east side of residential eet; house set far back on lot, nost in center of block; curving ht driveway; mature trees
COA DATE	
COA DECISION	
PREPARER	Lara Ramsey
PREPARER ORGANIZATION	GRANACKI HISTORIC CONSULTANTS
SURVEYDATE	11/7/2007
SURVEYAREA	NAPERVILLE





DIGITAL PHOTO ID

\lmages\wright12 DIGITAL PHOTO ID3

\Images\wright126n(3 ).jpg

\Images\wright126n(4 ).jpg

126 WRIGHT DIGITAL PHOTO ID2

\lmages\wright12 DIGITAL 6n(2).jpg PHOTOID4

STREET #	619				A TO THE	X 16.
DIRECTION	E				M. Care	
STREET	FRANKLIN		LYLA	1		<b>4</b>
SUFFIX	AV		J M	1	4.7%	
PIN				1	E	
LOCAL SIGNIFICANCE RATING POTENTIAL IND NR? (Y or N)	PS N					
Contributing to a NR DISTRICT? Contributing seco	C ndary structure	? [-				
Listed on existing SURVEY?			2 -		1000	-
			<b>GENERAL INI</b>	FORM	<u> MATION</u>	
CATEGORY b	uilding		CURRENT FUNC	ΓΙΟΝ	Education - school	
CONDITION	CONDITION good HISTORIC FUNCTION Education - education-related					related
INTEGRITY r						
SECONDARY STRUCTURE						
			— ARCHITECTUR	AL D	ESCRIPTION	
ARCHITECTURA CLASSIFICATIO		enaissance Revival			PLAN	irregular
	Italian Ne	ilaissalice itevivai			NO OF STORIES	3
DETAILS	1000				ROOF TYPE	Combination
BEGINYEAR	c. 1930				ROOF MATERIAL	Ceramic Tile
OTHER YEAR	Surveyor	/Sanhara			FOUNDATION	Concrete
DATESOURCE WALL MATERIA		Brick			PORCH	West Side
WALL MATERIA		BIICK			WINDOW MATERIA	AL Vinyl
WALL MATERIAL 2 (current)  WALL MATERIAL (original)  Brick				WINDOW MATERIA	AL	
WALL MATERIAL (original)  WALL MATERIAL 2 (original)				WINDOW TYPE	double hung	
WALLMATERIA	LL 2 (or iginal)				WINDOW CONFIG	1/1
SIGNIFICANT FEATURES						t 3rd story sill level; 2-story ttry; shed dormer on south
ALTERATIONS	Replacement v	windows in original c	ppenings; replacement	doors;	large 1 story rear additi	ion connected to 26 N. Wright

### **HISTORIC INFORMATION**

HISTORIC NAME	Kroehler, Peter Memorial Dormitory
COMMON NAME	Krejci Academy
COST	
ARCHITECT	
ARCHITECT	2
BUILDER	
ARCHITECT SOURCE	
	Building was originally dormitory for North Central College.
PERMITS	
LANDSCAPE	Midblock on north side of residential street; front and east sidewalks;
COA DATE	
COA	
DECISION	
PREPARER	
PREPARER ORGANIZAT	ION
SURVEYDAT	
SURVEYARE	Α







DIGITAL PHOTO ID

DIGITAL PHOTO ID2 \lmages\franklin6 DIGITAL PHOTO ID3

\lmages\franklin6 DIGITAL 19e(2).jpg PHOTOID4

SITAL \lmages\franklin619e( 3).jpg

\Images\franklin619e( 4).jpg

619 E FRANKLIN