City of NAPERVILLE

				MIL	IIISTORICAL SURVET	
STREET #	127		Mile Comment of the C	==	1 1 1 1 1 1 1 1 1 1	
DIRECTION	S					
STREET	COLUMBIA					
SUFFIX	ST					
PIN	0818409004				一 1/3 毫	
LOCAL SIGNIFICANCE RATING POTENTIAL IND NR? (Y or N) Contributing to a	C N					
NR DISTRICT?			THE WAY			
Contributing secondary structure?						
Listed on existing SURVEY? Local District; NR District						
			GENERAL INFORM	MATION		
CATEGORY building			CURRENT FUNCTION	Domestic - single dwelling		
CONDITION good			HISTORIC FUNCTION	Domestic - single dwelling		
INTEGRITY minor alterations REASON for SIGNFICANCE						
SECONDARY STRUCTURE Detached garage						
ARCHITECTURAL DESCRIPTION						
ARCHITECTURA CLASSIFICATION				PLAN	rectangular	
DETAILS				NO OF STORIES	2.5	
BEGINYEAR c. 1915				ROOF TYPE	Hipped	
OTHER YEAR				ROOF MATERIAL	Asphalt - shingle	
DATESOURCE Surveyor				FOUNDATION	Stucco	
WALL MATERIA	L (current)	Stucco		PORCH	Front entry canopy	
WALL MATERIAL 2 (current)				WINDOW MATERIA		
WALL MATERIAL (original) Stucco		Stucco		WINDOW MATERIA		
WALL MATERIAL 2 (original)				WINDOW TYPE	Double hung/awning	
F				WINDOW CONFIG	3/1; 6/1; 4-light	
			ng eaves; south side hipped de t awning windows; 1-story so		y canopy with large brackets;	
ALTERATIONS	One story rear addition (historic); replacement porch stoop, railings, walls (not historic)					

HISTORIC INFORMATION

Instance in Ormanon
HISTORIC NAME
COMMON NAME
COST
ARCHITECT
ARCHITECT2
BUILDER
ARCHITECT SOURCE
HISTORIC INFO
PERMITS
LANDSCAPE Northwest corner of Columbia and Chicago; front and south sidewalks; rear driveway; privacy plantings; mature trees
COA DATE
COA DECISION
PREPARER Lara Ramsey
PREPARER GRANACKI HISTORIC CONSULTANTS
SURVEYDATE 11/5/2007
SURVEYAREA NAPERVILLE
127 S COLUMBIA





DIGITAL PHOTO ID

DIGITAL PHOTO ID2 \Images\columbi a127s(2).jpg

\Images\columbi a127s.jpg DIGITAL PHOTO ID3

DIGITAL PHOTOID4 \Images\columbia127 s(3).jpg

\Images\columbia127 s(4).jpg