City of NAPERVILLE

STREET #	209		1 484				
DIRECTION	N	<					
STREET	BRAINARD						
SUFFIX	ST						
PIN	0818132011						
LOCAL SIGNIFICANCE RATING	S						
POTENTIAL IND NR? (Y or N)	N						
Contributing to a NR DISTRICT?	C						
Contributing seco Listed on existing SURVEY?	IHSS (O); Local District; NR	The state of the s					
GENERAL INFORMATION							
CATEGORY	puilding	CURRENT FUNCTI	ON Domestic - single dwel	ling			
CONDITION	excellent	HISTORIC FUNCTION Domestic - single dwelling					
INTEGRITY minor alterations and addition(s) REASON for SIGNFICANCE SECONDARY STRUCTURE REASON for SIGNFICANCE Detached garage Detached garage REASON for SIGNFICANCE SIGNFICANCE Excellent example of Colonial Revival residence in the historic district. Simple, yet stately, example. Listed on Illinois Historic Structures Survey.							
_		ARCHITECTURA	L DESCRIPTION				
ARCHITECTURA CLASSIFICATIO			PLAN	Rectangular			
	Colonial Revival		NO OF STORIES	2			
DETAILS	1005		ROOF TYPE	Side gable			
BEGINYEAR	c. 1925	ROOF MATERIAL	Asphalt - shingle				
OTHER YEAR		FOUNDATION	Concrete - poured				
DATESOURCE Surveyor PORCH -							
WALL MATERIAL (current) Brick			WINDOW MATERIA	AL Wood			
WALL MATERIA			WINDOW MATERIA	AL			
WALL MATERIAL (original) Brick			WINDOW TYPE	Double hung/awning			
WALL MATERIAL 2 (original)			WINDOW CONFIG	WINDOW CONFIG 6/1; 3-light			
SIGNIFICANT Side gable roof with cornice returns; symmetrical front façade; front entry with classical surround and carved brackets; historic 6/1 wood double hung windows							
ALTERATIONS	Replacement front steps and rai	ling (not historic); 1 story re	ear addition				

City of NAPERVILLE

STREET#	209			71 K 1 **		- ×7. /		
DIRECTION	N		ST.	. 9	-	-		
STREET	BRAINARD							
SUFFIX	ST							
PIN	0818132011			XXII E		age!	THE RESERVE AS	
LOCAL SIGNIFICANCE RATING	S							
POTENTIAL IND NR? (Y or N)	N							
Contributing to a NR DISTRICT? Contributing seconds.	C ndary structure	? NC						
Listed on existing SURVEY? [HSS (O); Local District; NR								
GENERAL INFORMATION								
CATEGORY b	ouilding		CURREN	T FUNCTIO	N Domestic - sir	ngle dwelli	ng	
CONDITION e	CONDITION excellent HISTORIC FUNCTION				N Domestic - sir	Domestic - single dwelling		
INTEGRITY n	ninor alterations	s and addition(s)	REASON				al Revival residence in the	
SIGNFICANCE historic district. Simple, yet stately, example. Listed on Illinois Historic Structures Survey. SECONDARY Detached garage								
			ARCHITE	CTURAL	DESCRIPTI	ON		
ARCHITECTURA CLASSIFICATIO		Revival			PLAN		Rectangular	
DETAILS					NO OF STO	RIES	2	
	c 1925				ROOF TYP	E	Side gable	
BEGINYEAR c. 1925				ROOF MAT	ERIAL	Asphalt - shingle		
OTHER YEAR	Surveyor				FOUNDATI	ON	Concrete - poured	
DATESOURCE		Brick			PORCH		-	
WALL MATERIA		DIICK			WINDOW N	WINDOW MATERIAL Wood		
WALL MATERIAL 2 (current)					WINDOW N	WINDOW MATERIAL		
WALL MATERIAL (original) Brick			WINDOW 1	WINDOW TYPE Double hung/awning				
WALL MATERIAL 2 (original)			WINDOW C	WINDOW CONFIG 6/1; 3-light				
IGNIFICANT EATURES Side gable roof with cornice returns; symmetrical front façade; front entry with classical surround and carved brackets; historic 6/1 wood double hung windows								
ALTERATIONS		ront steps and raili cement (admin. app				(admin. a	pproved COA# 11-3735)	

HISTORIC INFORMATION

HISTORIC INFORMATION					
HISTORIC NAME					
COMMON NAME					
COST					
ARCHITECT					
ARCHITECT2					
BUILDER					
ARCHITECT SOURCE					
HISTORIC INFO					
PERMITS					
School; front	rner of Brainard and and south sidewalks; wrought iron fence; ature trees				
COA DATE					
COA DECISION					
PREPARER Lara Rams	TOW.				
	KI HISTORIC				
ORGANIZATION CONSULT	ANTS				
SURVEYDATE	11/28/2007				
SURVEYAREA NAPERVII	LE				
209 N BRAINARD	BRAINARD				





DIGITAL PHOTO ID

DIGITAL PHOTO ID2

\lmages\brainard 209n(2).jpg DIGITAL PHOTOID4

\lmages\brainard DIGITAL 209n.jpg PHOTO ID3

\Images\brainard209 n(3).jpg

\Images\brainard209 n(4).jpg